# State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

Sundry Notices and Reports on Wells			
		API	# (assigned by OCD) 30-045-20716
1. Type of Well GAS		5.	Lease Number B-11625-21
GAD		6.	
2. Name of Operator		7.	Lease Name/Unit Name
BURLINGTON RESOURCES			Patterson C Com
2 111		8.	Well No. # 1
3. Address & Phone No. of Operat PO Box 4289, Farmington, NM		9.	Pool Name or Wildcat Blanco Pictured Cliffs
4. Location of Well, Footage, Se	C. T. R. M	10	Elevation:
990'FSL, 990'FEL, Sec. 2, T-3		10.	Bigvacion.
330 122, 330 122, 330 2, 1	,		
Type of Submission	Type of Act	ion	
_x_ Notice of Intent	_X_ Abandonment	Change of Pla	
	Recompletion	New Construct	tion
Subsequent Report		Non-Routine	
ndus 1 Abandanmant	Casing Repair	Water Shut of	
Final Abandonment	Altering Casing Other -	Conversion to	5 Injection
wellbore diagram.		DECE NAN 1 GOIL GOI DUST	
(This space for State Use) Approved by NIGHAL SIGNED BY ERNIE	(MEL4) Regulatory		
Motify OCD in	time to a	Fire 55	

### PLUG AND ABANDONMENT PROCEDURE

11-3-97

#### Patterson Com C #1

Blanco Pictured Cliffs 990'FSL and 990' FEL / SE, Sec. 2, T31N, R12W San Juan County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- Install and test rig anchors. Prepare blow pit. Comply with all NMOCD, BLM and Burlington 1. Resources safety rules and regulations.
- MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU 2. relief line to blow well down; kill with water as necessary. ND wellhead and NU BOP, test.
- TOOH and LD 1" tubing (134 joints, 2837'). Round-trip 4-1/2" wireline gauge ring to 2784'. 3.
- Plug #1 (Pictured Cliffs perforations and top, 2784' 2684'): Set wireline CIBP at 2784'. PU 4. and tally in hole with workstring; TIH open ended and tag CIBP. Load casing with water and circulate clean. Pressure test casing to 500#. If casing does not test, spot or tag subsequent plugs as appropriate. Mix and pump 10 sxs Class B cement and spot balanced cement plug above the CIBP. TOH with tubing.
- Plug #2 (Fruitland Coal top, 2475' 2375'): Perforate 3 squeeze holes at 2475'. If casing 5. tested, then establish rate into squeeze holes. Set 4-1/2" wireline cement retainer at 2425'. RIH with tubing, sting into retainer and then establish rate into squeeze holes. Mix 36 sxs Class B cement and squeeze 24 sxs cement outside 4-1/2" casing and leave 12 sxs cement inside casing to cover Fruitland top. TOH with tubing.
- Plug #3 (Kirtland and Ojo Alamo tops, 1073' 925'): Perforate 3 squeeze holes at 1073'. 6. Establish rate into squeeze holes. Set 4-1/2" wireline cement retainer at 1023'. TIH with tubing, sting into retainer and then establish rate into squeeze holes. Mix 50 sxs Class B cement and squeeze 35 sxs outside 4-1/2" casing and leave 15 sxs inside to cover Kirtland and Ojo Alamo tops. TOH with tubing.
- Plug #4 (Surface Casing at 108'): Perforate 3 squeeze holes at 158'. Establish rate out 7. bradenhead valve. Mix and pump approximately 45 sxs Class B cement down 4-1/2" casing from 158' to surface, circulate good cement out bradenhead valve. Shut well in and WOC.
- ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to 8. comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

Recommended: M. & Kintuf
Operations Engineer

Approval:

## Proposed P&A DPNO 57773

# Blanco Pictured Cliffs SE, Section 2, T-31-N, R-12-W, San Juan County, NM

Long: / Lat:

Today's Date: 11-3-97

Spud: 12-10-70

Completed: 12-22-70 Elevation: 6272' (GL)

Logs: IEL, CDL, CBL, GR

12-1/4" Hole

6-3/4" Hole

Workovers: None

Ojo Alamo @ 975'

Kirtland @ 1023'

Fruitland Coal @ 2425'

Pictured Cliffs @ 2831'

PBTD 2976

TD 2983'

8-5/8" 24#, Csg. set @ 108' Cmt w/ 100 sxs (Circulated to Surface)

Perforate @ 158'

Plug #4 158' - Surface Cmt with 45 sxs Class R

Plug #3 1073' - 925' Cmt with 50 sxs Class B,

35 sxs outside casing and 15 sxs inside

Cmt Retainer @ 1023'

Perforate @ 1073'

Plug #2 2475' - 2375' Cmt with 36 sxs Class B, 24 sxs outside casing and 12 sxs inside

Cmt Retainer @ 2425'

Perforate @ 2475'

TOC @ 2550' (CBL)

Set CIBP at 2784'

Plug #1 2784' - 2684' Cmt with 10 sxs Class B

Pictured Cliffs Perforations: 2834' - 2856' w/ 4 SPF

4-1/2" 10.5#, Csg. Set @ 2983' Cmt w/ 350 sxs

(Perforated 2 Squeeze Holes @ 2814' Squeezed w/ 300 sxs)

### Current

#### **DPNO 57773**

### Blanco Pictured Cliffs SE, Section 2, T-31-N, R-12-W, San Juan County, NM

Long: / Lat:

Today's Date: 11-3-97

Spud: 12-10-70 Completed: 12-22-70

Elevation: 6272' (GL)

Workovers: None

Logs: IEL, CDL, CBL, GR

12-1/4" Hole

8-5/8" 24#, Csg. set @ 108' Cmt w/ 100 sxs (Circulated to Surface)

Note: Bradenhead failure reported.

Ojo Alamo @ 975'

Kirtland @ 1023'

Fruitland Coal @ 2425'

Pictured Cliffs @ 28311

1" Tubing Set at 2837' (134 joints, line pipe)

TOC @ 2550' (CBL)

Pictured Cliffs Perforations: 2834' - 2856' w/ 4 SPF

6-3/4" Hole 4-1/2" 10 5#, Csg. Set @ 2983' Cmt w/ 350 sxs TD 29831

PBTD 2976

(Perforated 2 Squeeze Holes @ 2814' Squeezed w/ 300 sxs)