Form 9-331 (May 1963)

## UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE\*
(Other instructions on reverse side)

Form approved.
Budget Bareau No. 42-31424.
LEASE DESIGNATION AND SERIAL NO.

DEPART	MENT OF THE INTERIOR verse side)	5. LEASE DESIGNATION	AND SERIAL NO.		
(	GEOLOGICAL SURVEY	SF 078507			
(Do not use this form for Drote	FICES AND REPORTS ON WELLS estals to drill or to deepen or plug back to a different reservoir. ATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME		
1.		7. UNIT AGREEMENT NA	ME		
OIL GAS WELL TO OTHER	San Juan 32-	9 Unit			
2. NAME OF OPERATOR		8. FARM OR LEASE NAM	S. FARM OR LEASE NAME		
El Paso Natural Gas C 3. ADDRESS OF OPERATOR	ompany	9. WELL NO.			
P. O. Box 990, Farmin	81	81			
4. Location of well (Report location See also space 17 below.) At surface	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)		Undes Fruitland		
1800'/S, 1680'/W, Sec	. 26, T32N, R10W	11. SEC., T., R., M., OR E SURVEY OR AREA	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
		SW 26-32N-10W			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE		
	6961' GL	San Juan	New Mexico		
16. Check A	ppropriate Box To Indicate Nature of Notice, Report	, or Other Data			

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON	X	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	REPAIRING WELL  ALTERING CASING ABANDONMENT*		

(Other)

(Other)

(Other)

(Other)

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

\*\*The completion of Report results of multiple completion on Well Completion of Report and Log form.)

## Procedure to Plug & Abandon

Move on location and rig up. Spot cement plug across Fruitland perfs from 3436' to 3684'.

Shoot casing off at free point.

Spot cement plug over casing stub.

Pull up and spot cement plug across Ojo Alamo from 2100' to 2210'.

Spot cement plug in surface pipe from 150' to surface.

Set dry hole marker.



				•		
18. I hereby certify that the foregoing is true and correct SIGNED John J. Jellerson	) TITLE	Production	Engineer	_ DATE _	4-6-78	
(This space for Federal or State office use)						
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		,	DATE _		

