Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

7 0 7 1000 TT 11 1714 000 40	ION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs NM 88240 P.O. Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		30-045-21321
		5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON W	ELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP DIFFERENT RESERVOIR. USE "APPLICATION FOR (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL GAS WELL OTHER		San Juan 32-7 Unit 009260
2. Name of Operator		8. Well No.
Phillips Petroleum Company 3. Address of Operator	017654	SJ 32-7 Unit #43
	87401	Basin Dakota 71599
4. Well Location Unit Letter B: 1060' Feet From The No.	orth Line and 16	60' Feet From The East Line
Section 21 Township 32N	Range 7W	NMPM San Juan, County
10. Elevation (Show with	hether DF, RKB, RT, GR, etc	c.)
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
NOTICE OF INTENTION TO.	¬	<u></u>
PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON	REMEDIAL WORK	L ALTERING CASING L
TEMPORARILY ABANDON CHANGE PLANS		OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CE	EMENT JOB
OTHER: Reperforate Dakota	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.		
POOH with 1-1/2" production tubing. RIH wi POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing.	⁄abandon lower Da	kota. Reperforate Dakota from
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing.	⁄abandon lower Da	kota. Reperforate Dakota from th azid/KC1 ballouts. POOH with
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown	⁄abandon lower Da	kota. Reperforate Dakota from
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing.	⁄abandon lower Da	kota. Reperforate Dakota from th azid/KC1 ballouts. POOH with
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing.	abandon lower Da each 10'zone wi	kota. Reperforate Dakota from th azid/KCl ballouts. POOH with DECELVED MAR 2 2 1995 OOL COM, DOOY
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing. A workover pit may be required.	abandon lower Da each 10'zone wi	kota. Reperforate Dakota from th azid/KCl ballouts. POOH with DECELVED MAR 2 2 1995 OOL COM, DOOY
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing. A workover pit may be required. I hereby certify that the information above is true and complete to the best of my known signature. TYPE OR PRINT NAME Ed Hasely	abandon lower Da each 10'zone wi	kota. Reperforate Dakota from th azid/KCl ballouts. POOH with DECEIVED MAR 2 2 1995 OIL CONS DIV.
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing. A workover pit may be required. I hereby certify that the information above is true and complete to the best of my known signature.	abandon lower Da each 10'zone wi	Reperforate Dakota from th azid/KCl ballouts. POOH with DECEIVED MAR 2 2 1995 OIL CONSTANT BING DING DING BING BATE 3-22-95
POOH. Set CIBP at +/- 7980' to permanently 7828' - 7838' and 7873' - 7883'. Breakdown workstring and rerun production tubing. A workover pit may be required. I hereby certify that the information above is true and complete to the best of my known signature. TYPE OR PRINT NAME Ed Hasely	wledge and belief. TITLE Envir./Regulation	kota. Reperforate Dakota from th azid/KCl ballouts. POOH with DECENVED MAR 2 2 1995 OUL CONSIDER atory Engineer DATE 3-22-95 TELEPHONE NO.505-599-3454