

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42 R1424.  
5. LEASE DESIGNATION AND SERIAL NO.  
Ute Mountain Tribal  
MOO-C-1420-0623  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR El Paso Natural Gas Company		8. FARM OR LEASE NAME Pinon Mesa D	
3. ADDRESS OF OPERATOR PO Box 990, Farmington, NM 87401		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 850'S, 1690'W		10. FIELD AND POOL, OR WILDCAT Basin Dakota	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T-31-N, R-14-W NMPM	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5819'GL		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

It is intended to plug and abandon the subject well because of its non-productivity in the following manner:

Spot a cement plug across the Dakota formation, pressure displace cement through the Dakota perforations.  
Spot a cement plug across the Gallup perforations inside the casing. Determine the free point of 4 1/2" casing by the stretch method. If casing is free at or below 450', shoot off and recover.  
Spot a cement plug on the casing stub that will cover the Mesa Verde and fill to the bottom of the surface casing.  
Place a cement plug at the surface, erect a dry hole marker and clean up location.  
If 4 1/2" casing is not free below 450', perforate squeeze holes. Spot a cement plug across the squeeze holes. Pressure displace cement into the formation to isolate the Mesa Verde.  
Perforate squeeze holes opposite the base of the surface casing. Spot a cement plug across the squeeze holes and pressure displace cement into the formation.  
Place a cement plug at the surface. Erect a dry hole marker and clean up location.

18. I hereby certify that the foregoing is true and correct

SIGNED *A. D. Busco*

TITLE Drilling Clerk

DATE September 29, 1976

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

