

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

MOO-C-1420-0624

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Ute

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pinon Mesa C

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Undes. Fruitland

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 25, T-31-N, R-14-W
N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER Dry Hole

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 990, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1190'S, 1020'E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5705' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

☐
☐
☒
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

☐
☐
☐

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The recommended procedure to plug and abandon this well:

Spot a 75 sk. cement plug at 700' (89 ft.³ fills 262' in 7 7/8" hole), to cover Pictured Cliffs.Spot a 25 sk. cement plug at 150' across surface casing shoe. (30 ft.³ fills 87')

Remove casing head and place a 10 sk. cement plug at the surface. Install P & A marker.

Restore surface location.

Note: Oral approval by J. W. Long in telephone conversation with L. O. VanRyan on 03-27-76.

18. I hereby certify that the foregoing is true and correct

SIGNED

A. P. Duico

TITLE

Drilling Clerk

DATE March 29, 1976

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side