UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	ices and Reports on Wells	7	
1. Type of Well GAS	070 7741C.1, N	5.	SF-078604
		7.	Unit Agreement Name
2. Name of Operator BITRIINGTON	•		
アンア・アンプ・アナンア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・ア・	& GAS COMPANY	•	Mall Mana & Mumban
3. Address & Phone No. of Opera		8.	Well Name & Number Scott #2A API Well No.
PO Box 4289, Farmington, NM	1 8/499 (505) 326-9/00	۶.	30-045-21994
4. Location of Well, Footage, S 1650'FSL, 980'FEL, Sec.31, T			Field and Pool Blanco Pictured Cliffs Blanco Mesaverde
-		11.	County and State San Juan Co, NM
and wellbore diag	gle the subject well accord ram. A down hole commingling	ng order wil	attached procedure l be applied for
with the New Mexi	co Oil Conservation Divisio	on.	
		V \$	舞送 = 7 代 コン
			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	e foregoing is true and cor		or_Date 2/25/97
(This space for Federal or Stat APPROVED BY /S/ Duane W. Spe	te Office use)	Date	MAR - 5 1997
CONDITION OF APPROVAL, if any:			
Meed DHC orde	NMOCO		

Scott 2A

Mesaverde / Pictured Cliffs Unit I, Section 31, T32N, R10W Lat. 36-56.35', Long. 107-55.73' Commingle Workover Procedure 01/06/97

- 1. Hold safety meeting. Comply with all MOI, BLM and NMOCD rules and regulations. Dig flowback pit or set flowback tank. Install 1x400 bbl rig tank and fill w/ 2% KCL water.
- 2. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water as necessary. ND WH and NU BOP.
- 3. TOOH w/ 1-1/4" Pictured Cliffs tubing set at 2883'. TOOH w/ 2-3/8" Mesaverde tubing set at 5322' and Baker Model "G" seal assembly and lay down. Inspect tubing and report any scale build up. (An acid wash may be necessary and will be pumped in step 6.)
- 4. PU Baker CJ milling tool on 2-3/8" tubing and TIH. Mill on Baker Model "D" packer with air/mist (minimum mist rate is 10 Bbls/hr). Recover packer and TOOH.
- 5. PU 3-7/8" bit and 4-1/2", 10.5# casing scraper on 2-3/8" workstring and clean out to PBTD of \pm 5398'. Obtain pitot gauge and record on morning report.
- 6. If tubing did not have excessive scale in Step 3, skip to Step 7. RU acid truck and pump 300 gallons of inhibited 15% HCL down tubing followed by air/mist. Allow acid to spend for 15 minutes then displace from hole.
- 7. PU above the Pictured Cliffs perforations @ 2805' and flow the well naturally, making short trips for clean up when necessary. Obtain pitot gauge from MV and PC after clean up. TOOH w/ bit and scraper.
- 8. TIH with one joint of 2-3/8", 4.7#, J-55 tubing w/ expendable check, a seating nipple (one joint off of bottom), then the remaining 2-3/8" production tubing. CO to PBTD. Land tubing near bottom perforation (5322').
- 9. ND BOP, NU single tubing hanger wellhead. Pump off expendable check. Obtain final pitot up the tubing. If well will not flow on it's own, make swab run to seating nipple. If a swab run is not necessary, run a broach on slickline to ensure that the tubing is clear. RD and MOL. Return well to production.

Recommend:	Production Engineer
Approval:	
Прргочин	Drilling Superintendent
Approval:	Northwest Basin Team Leader

Contacts:

Engineers:

Mary Ellen Lutey

Office - (599-4052)

Home - (325-9387)

Pager - (324-2671)

Lori Lantz

Office - (599-4024)

Home - (324-0692)

MEL:mel

Scott #2A Unit 1, Sec. 31, T32N, R10W

Location:

1650' FSL,980' FEL

San Juan County, NM

Latitude: Longitude: 36-56.35 107-55.73

Current Field:

Pictured Cliffs/Mesaverde

Logs Run: Completed: IES, FDC-GR, CB,TS

Spud:

4/21/76

Elev KB:

6/1/76

Elev GL: TD:

5998' 5416' PBTD:

5398'

CASING RECORD:

Hole Size 12-1/4"

8-3/4"

Casing Size 9-5/8"

Weight 40# 20#

<u>Grade</u> KS KS

Depth Set 226' 3162'

Cmt Vol 190 sx 232 sx

Cmt Top Surface (circ.) Surface (circ.)

LINER RECORD:

Hole Size 6-1/4"

1-1/4" PC

Casing Size 4-1/2"

Weight 10.5#

Grade KE Liner Depth Set 2998'-5416' Cmt Vol 239 sx

Cmt Top liner top

TUBING RECORD:

Tubing Size 2-3/8" MV

Weight 4.7# 2.75#

Grade J-55 J-55

Depth Set 5322' 2883

<u>Joints</u> 174

Other

Depth

92

Baker Model 'D' PKR

2920'

FORMATION TOPS:

Ojo Alamo Kirtland

Fruitland

1149' 1200' 2340'

2800' **Pictured Cliffs** 4594' Cliffhouse 4690' Menefee

Pt Lookout Gallup Dakota

5018

Completions:

Point Lookout Perfs: 4902'-5322'

Frac'd w/76,600 gal water and 65,000# sand.

Cliff House Wenefee Perfs: 4455'-4833'

Frac'd w/49,500 gal water & 45,000# sand.

Pictured Cliffs Perfs: 2805'-2883'

Frac'd w/59,700 gal water and 40,000# sand.

Cementing Information

9-5/8" csg: 190 sx Class B w/.25# gel-flakes/sx, 3% CaCl2.

7" csg: 162 sx Class B 65-35 POZ, 12% gel, 1/4 c.f. gilsonite/sx. 70 sx 2% CaCl, 1/4 c.f. gilsonite. 4-1/2" csg: 239 sx Class B w/4% gel, 1/4 c.f. fine gilsonite, 1% D-19. Reversed out 3 bbls cmt. Perf 2 Holes @ 2800': SQ w/668 c.f. Class B w/4% gel, 3% CaCl2. BH: SQ 360 c.f. Class B w/4% gel, 1/4 c.f. gilsonite, 3% CaCl2. Re-SQ holes @ 2800': 177c.f. Class B w/3% CaCl2.

Workover History:

1/27/96

Tubing Repair.

SCOTT #2A

AS OF 1/10/97 BLANCO PICTURED CLIFFS/MESAVERDE

1650' FSL, 980' FEL UNIT I, SEC 31, T32N, R10W, SAN JUAN COUNTY, NM

