14. PERMIT NO.

16.

UNITED STATES UNITED STATES SUBMIT IN TRIPLICATE Other instructions on reverse : ide) UNITED STATES

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY	NM 013642		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
OIL GAS WELL X OTHER	7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR Koch Exploration Company (Division of Koch Ind., Inc.)	8. FARM OR LEASE NAME		
3. ADDRESS OF OPERATOR P.O. Box 2256; Wichita, Kansas 67201	GARDNER 9. WELL NO.		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 	10. FIELD AND FOOL, OR WILDCAT Blanco Mesa Verde		
1775' FNL & 1550' FEL SW NE	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA		

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

KB 65271

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF		PULL OR ALTER CASING	[]	WATER SHUT-OFF	
FRACTURE TREAT		MULTIPLE COMPLETE			FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING
SH(r)T OR ACIDIZE		ABANDON*			SHOOTING OR ACIDIZING	ABANDON MENT*
REPAIR WELL		CHANGE PLANS		i I	(Other) Completion	
(Other) Squeeze off peris			(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - Kill well w/water.
 - Pull 1-1/2" & 2-3/8" tbg string & Baker "AD" pkr now set @ 5049'.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 6516'

- Set ret BP @ 3550' & spot two sx sand on top. 3.
- Set pkr @ 3300' & squeeze P.C. perfs 3433-3489 w/200 sx cmt.
- Reset pkr @ 2900' & WOC 6 hrs; squeeze Fruitland perfs 3068-3110 w/200 sx cmt.
- Drill out cmt. Test csg to 1000#.
- 7. Pull ret BP & run prod tbg.
- 8. Swab well in δ blow dry.
- Complete as Mesa Verde gas well only.

Sec. 31-32N-8W

San Juan

12. COUNTY OR PARISH 13. STATE

New Mexico

U. S. GEOLOGICAL SURVEY

	N. D. Schwerzer, Street, P.		
8. I hereby certify that the foregoing is the and correct SIGNED Dwell J. Schmidt	THE Operations Manager		0 7 77
(This space for Federal or State office use)	Titing Operacions Manage	DATE	3-1-11
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	