

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1180'FSL, 1520'FEL, Sec.34, T-32-N, R-10-W, NMPM

5. Lease Number
SF-078604

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Scott #19

9. API Well No.
30-045-22063

10. Field and Pool
Blanco Pict.Cliffs

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to plug and abandon the subject well according to the attached procedure and wellbore diagram.

RECEIVED
JUL - 7 1997

OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (ME15) Title Regulatory Administrator Date 6/25/97

(This space for Federal or State Office use)

APPROVED BY /s/ Duane W. Spencer

Title _____

Date JUL - 3 1997

CONDITION OF APPROVAL, if any:

PLUG AND ABANDONMENT PROCEDURE

6-2-97

Scott #19

Undesignated Pictured Cliffs

DPNO 45190A

1180' FSL and 1520' FEL / SE, Sec. 34, T32N, R10W

San Juan County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

1. Prepare blow pit. Comply to all NMOCD, BLM, and Burlington safety regulations. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with water as necessary. ND wellhead and install cementing valve.
2. Open bradenhead valve. Establish rate down 2-7/8" casing with 20 bbls water, record pump rate and pressure. Monitor bradenhead for flow. If no flow or blow, then pump 2 7/8" RCN balls in additional water and monitor pressure, rate and volumes pumped, to confirm perforations are taking water and there is not a casing leak. If the bradenhead flows water or there are other indications of a casing leak, then MO and RU pulling unit to use 1-1/4" IJ tubing workstring to plug the well.
3. **Plug #1 (Pictured Cliffs perforations, Fruitland, Kirtland, and Ojo Alamo tops, 2946' - 1200')**: Establish rate into perforations with water. Mix and pump 81 sxs Class B cement (20% excess) and bullhead cement down 2-7/8" casing, displace to 500' with water. Shut in well and WOC. Rig up mast truck and tag cement. Pressure test casing to 500#.
4. **Plug #2 (Surface Casing at 134')**: Perforate 2 squeeze holes at 184'. Establish circulation out bradenhead valve. Mix and pump approximately 55 sxs Class B cement down 2-7/8" casing, circulate good cement to surface. Shut in well and WOC.
5. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

Recommended: ME L. H. L.
Operations Engineer

Approval: J.S. L. 6/24
Drilling Superintendent

Scott #19

Proposed P&A

DPNO 45190A

Undesignated Pictured Cliffs

SE Section 34, T-32-N, R-10-W, San Juan County, NM

Today's Date: 6/2/97

Spud: 10/5/76


Completed: 12/8/76

Elevation: 6064' (GL)

Logs: Ind-Elec; CDL-GR: T.S.

Workover: None

Nacimiento @ Surf



Scott #19

Current

DPNO 45190A

Undesignated Pictured Cliffs

SE Section 34, T-32-N, R-10-W, San Juan County, NM

Today's Date: 6/2/97

Spud: 10/5/76

Completed: 12/8/76

Elevation: 6064' (GL)

Logs: Ind-Elec; CDL-GR; T.S.

Workover: None

Nacimiento @ Surf

8-5/8" 24# K-55 Csg set @ 134'
Cmt w/148 cf (Circulated to Surface)

12-1/4" hole

TOC @ 1075' (T.S.)

Ojo Alamo @ 1250'

Kirtland @ 1270'

7-7/8" hole to
unknown depth

Fruitland @ 2447'

Pictured Cliffs @ 2875'

Pictured Cliffs Perforations:
2882' - 2946' (9 holes)

PBTD 3011'

2-7/8" 6.4# J-55 Csg set @ 3022'
Cmt w/ 676 cf

6-3/4 hole

TD 3022'

