

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-045-23573
5. Indicate Type of Lease STATE FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Hutchin LS
8. Well No. 2
9. Pool name or Wildcat Blanco Pictured Cliffs
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 5822'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
BP America Production Company Attn: Mary Corley

3. Address of Operator  
P.O. Box 3092 Houston, TX 77253

4. Well Location  
Unit Letter G 1500 feet from the North line and 1540 feet from the East line  
Section 07 Township 31N Range 10W NMPM San Juan County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER:	OTHER:

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

BP America request permission to plug and abandon the subject well as per the following procedure:

- Check anchors. MIRU workover rig.
- Check and record tubing, casing, and bradenhead pressures.
- Blow down wellhead. Kill with water if necessary.
- Nipple down WH. NU BOPs. RU WL unit.
- RIH with 2-7/8" CIBP. Set CIBP at 2550'.
- PU 1-1/4" workstring.
- TIH with 1-1/4" workstring. Spot 500' cement plug (16.5 cu ft) above CIBP from 2050'-2550' to cover Picture Cliffs and Fruitland intervals. TOH.
- RU WL unit. RIH and perforate squeeze holes at 1275'.
- RIH and set 2-7/8" cement retainer at 1250'. TIH and sting into retainer. Squeeze Ojo Alamo with 85 cu ft cement. PU and spot 250' cement plug above cement retainer from 1000' - 1250'.
- TOH to 275'. Spot cement surface plug (9 cu ft) from 0' - 275'. TOH and LD workstring.
- ND BOP's. Cut off wellhead and install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Corley TITLE Sr. Regulatory Analyst DATE 09/10/2001  
Type or print name Mary Corley Telephone No. 281-366-4491

(This space for State use)

APPROVED BY CHARLES F. PETERIN TITLE DEPUTY OIL & GAS INSPECTOR DATE SEP 11 2002  
Conditions of approval, if any:

# Hutchin LS#2

Sec 7, T31N, R10W

API: 30-045-23573

5822' GL

est. TOC@surf

8-5/8" 24# K55 @224'

370 sxs cnt

## History:

Completed in Dec 1979

Apr 1992 - repaired bradenhead  
leak

1-1/4" IJ tbg 65' - 1120'

- cnt'd w/ 350 sxs cnt

TOC at surf (circ)

Est. TOC @1300' (4/1992 CBL)

## Pictured Cliffs Perforations

2600' - 2671' (9 holes)

frac'd w/ 61,000# sand

2-7/8" 6.4# J55 10rd @2819'

408 sacks cnt

PBID: 2809

updated: 4/11/01 jad

## NOTES:

1. Tubingless completion