

F

30-045-27969

07-09-90

F. Loc. T593/S; 1326/W Elev. 6608 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

Grav. _____ 1st Del. Gas _____
 BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____
 I.P. _____

TOPS		NiTD	X	Well Log	TEST DATA						
Ojo Alamo		C-103		Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104		Electric Log							
Fruitland				C-122							
Pictured Cliffs		Ditr		Dfa							
Chacra		Datr		Dac							
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		Acres W/320									

P
o
o

BasinFrCoal Co. SJ S 23 T 32N R 07W U L Oper. Phillips Petroleum Co. Lse. San Juan 32-7 Unit No. 212

San Juan 32-7 Unit #212

L-23-32N-07W

PHILLIPS PETROLEUM CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO:

NM-05220 et al. (WC)
3162.3-1 (019)

Phillips Petroleum Company
5525 Hwy 64 NBU 3004
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 248 SJ 29-6 Unit, sec. 15, T. 29 N., R. 6 W., Rio Arriba Co., NM,
lease NM-05220.
2. 253 SJ 29-6 Unit, sec. 29, T. 29 N., R. 6 W., Rio Arriba Co., NM,
lease NM-03040-A.
3. 251 SJ 29-6 Unit, sec. 23, T. 29 N., R. 6 W., Rio Arriba Co., NM,
lease SF-078284.
4. 250 SJ 29-6 Unit, sec. 23, T. 29 N., R. 6 W., Rio Arriba Co., NM,
lease SF-078284.
5. 214 SJ 30-5 Unit, sec. 5, T. 30 N., R. 5 W., Rio Arriba Co., NM,
lease SF-080066.
6. 212 SJ 32-7 Unit, sec. 23, T. 32 N., R. 7 W., San Juan Co., NM,
lease SF-078472.

As discussed with Gail Bearden of your company on, September 25, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

OCT. 03 1991

RECEIVED
OCT 4 1991
OIL CON. DIV.
DIST. 3

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

~~New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410~~