

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Koch Exploration Company

3. ADDRESS OF OPERATOR

3605 N. DUSTIN Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

80015-8251

14. PERMIT NO.

15. ELEVATIONS (Show whether BW, RT, OR, etc.)

GR. 6610

1. LEASE DESIGNATION AND SERIAL NO.

3F-079048-A

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

NA

7. UNIT AGREEMENT NAME

NA

8. FARM OR LEASE NAME

Gardner-C

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Basin Fruitland Pool

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

35-32N-9W

12. COUNTY OR PARISH

SAN JUAN

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PCLL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF*

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We have filed to drill this well through the coal and run & cement the pipe through the formation. We want to change the plan as follows. Drill 200' of 11 3/4 inch hole. Run 9 5/8" surface casing 200'. Cement with 8.3 sk. 100 CU. FT. 100% excess to circulate to surface. Drill 8 3/4" hole to top of coal zone. Run & cement 7" 26" casing at 3169' with 12.57 sk. 1508 Cu. ft. cement. 100% excess to circulate to surface. Drill 6 1/4" hole through the coal zone (3169-3494). Complete open hole, then run a 5 1/2" 17' liner from 3119 to 3494. DO NO CEMENT.

18. I hereby certify that the foregoing is true and correct

SIGNED

Delbert H. Eckard

TITLE

Dist. Prod. Supt.

DATE

8-29-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

FARMING