

A-27-32N-10W

MERIDIAN OIL INC.

10-04-90

F. Loc. 65/N; 300/E Elev. 6924 GL Spd. _____ Cu. ft. _____ Comp. _____ ID _____ PB _____
Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. I. _____ @ _____
Csg. Perf. _____ Prod. Stim. _____ T Gas _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas
I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil

TOPS		NITD	X	Well Log	TEST DATA							
Ojo Alamo		C-103		Plat	X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104		Electric Log								
Fruitland				C-122								
Pictured Cliffs		Ditr		Dfa								
Chacara		Datr		Dac								
Cliff House		1. T.R. - 3000000 #1 NSP-R-4314 2/D- E/305.02 Acres										
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												

**P
o
o
l**

0 Cedar Hill
1 Base Fr Coal Co. SJ S 27 T 32N R 10W UA Oper. Meridian Oil Inc. m. so. Payne

No. 271



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO
SF-078772 et al. (WC)
3162.3-1 (019)

RECEIVED

OCT 15 1991

OCT 11 1991

Meridian Oil Inc.
P.O. Box 4289
Farmington, NM 87499

**OIL CON. DIV
DIST. 3**

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 278 Rosa Unit Com, sec. 33, T. 32 N., R. 6 W., San Juan Co., NM, lease SF-078772.
2. 221 Payne, sec. 22, T. 32 N., R. 10 W., San Juan Co., NM, lease SF-080517.
3. 271 Payne, sec. 27, T. 32 N., R. 10 W., San Juan Co., N.M., lease SF-080517.

As discussed with Peggy Bradfield of your company on, October 9, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

CC:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION