Submit 3 Copies

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

to Appropriate District Office	Energy, windows and water and	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Revised 1 1 07
DISTRICT I	OIL CONSERVATIO	N DIVISION	
P.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco St.		WELL API NO. 30-045-11201
DISTRICT II	Santa Fe, NM 87505		5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210			STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
·	IOSO AND DEDODTO ON WELL		B111-24-24
	ICES AND REPORTS ON WELL		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Wright State Com
1. Type of Well:			
OÎL GAS WELL X	OTHER		
2. Name of Operator			8. Well No.
Taurus Exploration, U.S.A.,	Inc.	-	1
3. Address of Operator 2198 Bloomfield Highway; Far	rmington, NM 87401		9. Pool name or Wildcat Basin Dakota
4. Well Location		17	oo East
Unit Letter B 100	D Feet From The North	Line and1/	80 Feet From The East Line
26	Township 32 North Ra	nge 13 West	NMPM San Juan County
Section 36	Township 32 NOTUI Ra 10. Elevation (Show whether	ILEV	TANKE THE PROPERTY OF THE PROP
	10. Elevation (Show whether	5847 GL	<u> </u>
11. Check At	propriate Box to Indicate	Nature of Notice,	, Report, or Other Data
_	NTENTION TO:		SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GIOPNS. U PLUG AND ABANDONMENT U
PULL OR ALTER CASING		CASING TEST AND C	
PULL ON ALTER CASING	П		Г
OTHER:		OTHER:	
12. Describe Proposed or Completed Or	erations (Clearly state all pertinent det	ails, and give pertinent da	ates, including estimated date of starting any proposed
work) SEE RULE 1103.			
The Dakota zone has bee	n non-productive since 1973	•	
It is intended to plug	the Dakota and make a single	e Mesa Verde Comp	letion as follows:
1) MIRU. TOH and lay	down Mesa Verde tubing.		
Establish injection	rate into Dakota. Release	seal assembly and	d TOH.
3) Set retainer at 580	O'. Squeeze off Dakota wit	h 130 sks cement.	Cap retainer with 2 sks. TOH.
4) Run 2 3/8" tubing t	o 4780'.		
			DEWED
			内にいる。
		-	M 19
	1		APR - 8 1998 -
1	\		OUT GOLD DOUG
			OIL CON. DIV.
I hereby certify that the information above is	true and complete to the best of my knowledge	e and belief.	DIN. 3
SIGNATURE DAY NO DA	шт	LE Production Sup	etintendent DATE 4/6/98
TYPE OR PRINT NAME GARY W. Brir	- sk		TELEPHONE NO. 505-325-6800
THE ORTHOTOGRAPH M. DITT	<u> </u>		
(This space for State Use)	01-		
Oshama	Robinson	DEPUTY OIL & GAS	s inspector, dist. #3 APR - 8 1991
		LE	DATE