

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF-078312
2. NAME OF OPERATOR Aztec Oil & Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Drawer 570, Farmington, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1000' FNL & 1010' FEL		8. FARM OR LEASE NAME Hubbard
14. PERMIT NO.		9. WELL NO. #3
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6148' KB		10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde Basin, Dakota
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 15, T32N, R12W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other)

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* DK zone ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other)

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROPOSE TO:

Move in and rig up.
Pull 1-1/2" tubing.
Pick up 4-1/2" cement retainer and set at 7000'.
Trip in hole with tubing.
Squeeze Dakota zone with 35 sacks of cement.
Trip out of hole with tubing and lay down stinger.
Run tubing back to 5119'.
Rig down and return Mesa Verde zone to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Production Mgr.

DATE November 9, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 10 1977

*See Instructions on Reverse Side

U.S. Geological Survey
Farmington, N.M.