

Black Diamond Oil Co. #1 C-2229N-11W

This photograph was taken by Mr. Charles Gholson, Oil Conservation Division Field Representative, on April 11, 1978. The casing is corroded at the surface and water is flowing out onto the ground causing the black stain seen on the photo.

1. Source of pollution at surface
2. Sam from River within 200' yards
3. Threat of pollution to other underground strata

10" @ ?

TD 800'

30-045-07896-

C STATE NEW MEXICO
COUNTY San Juan SEC. 27 T. 29N R. 11W
FIELD OR AREA LOCATION 920' N, 1520' W
LEASE ? WELL NO. 1
COMPANY Black Diamond Oil SPD. 9-24-30 COMPLETED 3- -31
ELEV. 5420' T.D. 800' P.B.
CASING
SHOT OR ACID
PERF.
I.P.
PRODUCING FORM
PRODUCTIVE DEPTH OR INTERVAL

REMARKS:

Abandoned