

Form 2-551
(July 1962)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form 2-551
District Office (Form 2-551)
5. BUREAU OF LAND MANAGEMENT AND MINERAL RESOURCES

SP-978115

6. IF NECESSARY, ADDITIONAL OR OTHER DATA

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER	7. USE (Check appropriate)
2. NAME OF OPERATOR <i>Antec Oil & Gas Company</i>	8. FIELD OR LOCAL NAME <i>Granja</i>
3. ADDRESS OF OPERATOR <i>Boxer 570, Farmington, New Mexico</i>	9. WELL NO. <i>#4</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>990 FNL & 930 FNL, Section 7-31N-11W</i>	10. FIELD AND FOOT, OR SURVEY <i>Blanco Mesquedo</i>
14. PERMIT NO.	15. ELEVATIONS (Show whether FT, RT, GR, etc.) <i>6296 Gr</i>
	12. COUNTY OR PARISH, 13. STATE <i>San Juan New Mexico</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Redrill NY

☐
☐
☐
☐
☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐


☐
☐
☐
☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROPOSE TO:

1. Move On Rig & Pull Tubing.
2. Run Corrosion Log.
3. Squeeze Open Hole From 5054-5307.
4. Set Whipstock @ 4900'.
5. Cut Window & Drill To 5350'.
6. Run 3 1/2" Liner To T.D. With Top Approximately 4800'. Run Long String of 3 1/2".
7. Run Gamma-Neutron Log With Collar Log.
8. Perf & Frac Point Lookout Formation.
9. Clean Out.
10. Run Tubing & Put Back On Production.



RECEIVED

JUL 22 1970

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jac C. Gorman

TITLE

District Superintendent

DATE

July 20, 1970

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side