


# Americo Energy State T Battery Work Plan Unit K, Section 2, Township 15S, Range 37E Lea County, New Mexico

June 17, 2005



Prepared for:

Americo Energy Recepts
10940 Old Katy Road
Houston, Texas 77043



By:

Safety & Environmental Solutions, Inc. 703 E. Clinton Suite 102 Hobbs, New Mexico 88240 (505) 397-0510

# **TABLE OF CONTENTS**

l. C	ompany Contacts	.1
li.	Purpose	.1
III.	Background	.1
	Contaminant and Size of Area	
V.	Vertical and Horizontal Extent of Contamination	.1
VI.	Groundwater	.1
VII.	Action Plan	.2
	.Figures & Appendices	
	Figure 1 - Vicinity Map	.4
	Appendix A - Site investigation	. 3

☑ Microsoft Access = [Administrative /	Applications/Ord	lers)	district the second	<u> </u>
Elle Edit RBDMS Reports View Records Admi		***		
<b>ス・日 日 日 4 9 1 9 1 9 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1</b>	更 A H M 喝	<b>命 省 · (3) ·</b>	a take te	<u> </u>
Preview/Print Permit Administra	ative Applicati	ons/Orders	# <b>a</b> 9	7 P
casion contrator addition in pare the selection of the se		5422 P 4445 117		akarea andanin rada Kabalak
Application Rose Table Application Type 1	Cide No. 2. And # ECC	er this Processing C	ilēs jogni (Lea	I▼ Approvals (1.2%)
1R - Remediation Permit - Hobbs -	29	(Ozen	Jeriewer Johnson	□ ELM? □
AMERICO ENERGY RESOURCES LLC	E@cvd·	/Esp/	District Hobbs	<u></u>
y.Contact. <mark>Oscar</mark>	Pür ett.	Canel.	Jesting On <mark>Hobbs</mark>	
a Note S	/Addr.c.s			
ermit Cevel Actions and/or Data		avioninental Familie		
OG BOOK   EVENTS   WELLS (Non-ONGARD data to the righ	()   POOLS   MULTI-WELL	PROPERTY	WENDYORD I	JUK   MX1 OHO #
Facility	Bond No.	Cent Mail No.	Ot Eff	
UL-S-T-R County	Operator		Dt Exp	
Directions	- Guarantor	**************************************	Dt Rel	
	Amount	Typinst Statu	s GuarBndNo	
Well Specific and died and all Data				
			<del>- projection professional i</del>	
established in the state of the				
ecord: 14 4 192 (15 14 15 of 192 (Filtered)			TRUMPON STATE OF THE STATE OF T	
Applicant Contact Name				NUM

Microsoft Access - [RBD]	MS Surface Facilities Data I	Module)			_ <i>=</i> ×
B Elle Edit RBDMS Reports View	Records Admin Window Help				1.15
K-自904 % 新留後 5	· ● 和 ○ ● ● ● ● ● ● ● ● ● ● ● ● ● ● ● ● ●	命旨• 闭。		7	
Inspect Facility	Surface Facilitie	S   Date Max 1849/141	Facilities GIS	<b>₽</b> •	
Eddin/IS/fLWJ0521737124	Americo Energy State T Battery	GI-ST-R K	2 15 5 3	7 E	
	The second secon	A 🕶 🔤 County Lea		30	
1. The state of the second	AMERICO ENERGY RESOURCES LL	A CONTRACTOR OF THE PARTY OF TH	y Long		
. D → Open D ) Wir Soul		O Directions	80.65 - 12.548 \$100 Cap.204 \$18.40		
	phidefies Associated with This Passland C	Strong Refmits on Th	is nacility and envis	Walesconnius	
s (Flexev.)					
SC SuifOwn) 11				nais as aidings	
Location / Otr/Otr (etc.)	GW, Liepth 47 GW Impacti				
District Of - 2-GWQ 2Dsci		PNOTAS 3	Note that the second of the second		
🖵 Pits 🖧 Tanks 🕦 Sumps Contacts					
Pit No: Pit Type:	Status: - Ot Apprv:	Dt Open:			
Denied? ☐ Close Apprv'd? ☐ Clos	se Denied? 🗀 Not Built? 🗀 Dt Regist:	6 Mt Ext			100
Guide Lines?   Const Mat:	Fluid Type: Site R	ank: Dt Close:			
Leak Detect? .041504 Prior? Salt	Sect? Mud >9.5#? To Remain? Flds	Renord? Dewater? Lined			
Length A Width It De	pth it Capacity bbls Chlor	ppm TDS pp	m i i i i i i i i i i i i i i i i i i i		
OCD Remediation Action Le	evels: Benzene ppm BTEX	ppm, TPH pp	<u>m</u> ., 4	dialor Bolish	
Comments:	lofi e				
			KW Pages		
Record: H 4 790 P P P Of	790			NUM	ā [

### I. **Company Contacts**

Oscar Nosrati	Americo	713-984-9700	oscar.nosrati@americoenergy.com
Physics Allians	OFOL	EOE 007 0E40	hallan @aaai nuu aana

505-397-0510 <u>ballen@sesi-nm.com</u> Bob Allen SESI

### II. **Purpose**

The purpose of this work plan is to propose a plan for the cleanup of the area identified as the State T Battery. The site is located in Section 2, Township 15S, Range 37E, Lea County, New Mexico. The site is situated on a relatively level site.

### **III.** Background

Merit Energy received a Notice of Violation in mid-2004 regarding the condition of the battery inside the berm. SESI visited the site on July 28, 2004 and recorded visible hydrocarbon staining and 6 -10" of fluid covering the entire battery area. A oil sheen was visible on top of the fluid. At some time a previous release had overflowed the battery to the west. (See Photos) The area is now dry with visible staining. The battery is currently in use and owned by Americo Energy.

### IV. Contaminant and Size of Area

The suspected contaminant is produced fluids. The area inside the berm is approximately 22,000 square feet. No evidence of a current release is evident.

### V. **Vertical and Horizontal Extent of Contamination**

As reported in the Site investigation Report for Merit Energy dated April 28, 2005 SESI installed 7 test trenches at the State T Battery. The results of the analyses indicate the hydrocarbon contamination to be above the NMOCD guidelines in Test Trenches 1, 3, 4 and 6. The chloride concentrations are slightly elevated but should not present a threat MAR SHOWS ' to groundwater.

### VI. Groundwater

The following water level information was obtained from a database provided by the United State Geological Survey (USGS).

15S.37E.02.324214	19660218 42.09	15S.37E.04.113311	19930106 73.58
15S.37E.05.311334	19910308 72.54	15S.37E.06.211134	19960321 74.80
15S.37E.07.111324	19940106 75.84	15S.37E.08.211	19960105 69.41
15S.37E.08.21333	19910308 70.28	15S.37E.09.21112	19910308 68.80
15S.37E.09.431211	19960103 67.01	15S.37E.10.111332	19801003 62.34
15S.37E.11.333324	19910313 57.17	15S.37E.12.313221	19960110 52.48
15S.37E.14.232342	19860204 49.28	15S.37E.15.143423	19910313 63.76

In addition, there is a monitor well installed in Section 11 to the southeast of the subject site where groundwater was measured to be 68.27' from the top of casing on April 7, 2005.

### VII. Action Plan

Based on the characterization of the site, the cleanup level reached by the application of the "Guidelines for Remediation of Leaks, Spills and Releases" New Mexico Oil Conservation Division (NMOCD) – August 13, 1993 (Guidelines) to this site is 1000 parts per million (ppm) Total Petroleum Hydrocarbons (TPH). Application of the New Mexico Oil Conservation Division's ranking criteria for contaminated soils at this site is presented below:

Depth to Ground Water:	10 points
Distance to Well Head or Water Source:	0 points
Distance to Surface Water/Waterways:	0 points
Total Score:	10 points

SESI proposes the north end of the battery to be excavated to the point where a representative sample of the bottom and sidewalls indicate the TPH levels are no greater than 1000 ppm. The excavated soils will be transported off-site to an NMOCD approved facility. The remainder of the battery will be excavated to remove the highly contaminated/saturated soils to a depth no greater than 3' or 1000 ppm whichever is first encountered. The remainder will be delineated to document vertical extent. The excavated areas will then be backfilled with clean soil from off-site and contoured to grade.

The appropriate reports will be filed with the NMOCD upon completion.

## VIII. Figures & Appendices

Figure 1. - Vicinity Map Figure 2. - Site Plan Appendix A – Site Investigation Figure 1
Vicinity Map





Figure 2 Site Plan





**Merit Energy** 

State T Battery S2, T15S, R37E Lea County, New Mexico

Safety & Environmental Solutions, Inc.

Appendix A Site Investigation

# Merit Energy State T Battery Site Investigation Unit K, Section 2, Township 15S, Range 37E Lea County, New Mexico

**April 28, 2005** 



Prepared for:

Merit Energy 13727 Noel Road, Suite 500 Dallas, Texas 75240

By:

Safety & Environmental Solutions, Inc. 703 E. Clinton Suite 102 Hobbs, New Mexico 88240 (505) 397-0510

# **TABLE OF CONTENTS**

III. Purpose	I.	Company Contacts	1
III. Background  IV. Contaminant and Size of Area  V. Groundwater  VI. Work Performed  VII. Conclusions  VIII. Figures & Appendices  Figure 1 - Vicinity Map.  Figure 2 - Site Plan  Appendix A – Analytical Results			
IV. Contaminant and Size of Area  V. Groundwater			
VII. Conclusions  VIII. Figures & Appendices			
VII. Figures & Appendices  Figure 1 - Vicinity Map	٧.	Groundwater	1
VIII.Figures & Appendices  Figure 1 - Vicinity Map  Figure 2 - Site Plan  Appendix A – Analytical Results	VI.	Work Performed	1
Figure 1 - Vicinity MapFigure 2 - Site PlanAppendix A – Analytical Results	VII.	Conclusions	2
Appendix A – Analytical Results	VIII.	Figures & Appendices	3
Appendix B – Site Photos		Figure 1 - Vicinity Map	5
		Appendix B – Site Photos	7

## 1. Company Contacts

Chad Brister	Merit	972-628-1564	chad.brister@meritenergy.com
Bob Allen	SESI	505-397-0510	ballen@sesi-nm.com

### II. Purpose

The purpose of this site investigation is to identify the vertical and horizontal extent of contamination inside the bermed area at the State T Battery. The site is located in Section 2, Township 15S, Range 37E, Lea County, New Mexico. The site is situated on a relatively level site.

### III. Background

Merit Energy received a Notice of Violation in mid-2004 regarding the condition of the battery inside the berm. SESI visited the site on July 28, 2004 and recorded visible hydrocarbon staining and 6 -10" of fluid covering the entire battery area. An oil sheen was visible on top of the fluid. At some time a previous release had overflowed the battery to the west. (See Photos) The area is now dry with visible staining. The battery is currently in use and owned by Americo Energy.

### IV. Contaminant and Size of Area

The suspected contaminant is produced fluids. The area inside the berm is approximately 22,000 square feet. No evidence of a current release is evident.

### V. Groundwater

The following water level information was obtained from a database provided by the United State Geological Survey (USGS).

15S.37E.02.324214	19660218 42.09	15S.37E.04.113311	19930106 73.58
15S.37E.05.311334	19910308 72.54	15S.37E.06.211134	19960321 74.80
15S.37E.07.111324	19940106 75.84	15S.37E.08.211	19960105 69.41
15S.37E.08.21333	19910308 70.28	15S.37E.09.21112	19910308 68.80
15S.37E.09.431211	19960103 67.01	15S.37E.10.111332	19801003 62.34
15S.37E.11.333324	19910313 57.17	15S.37E.12.313221	19960110 52.48
15S.37E.14.232342	19860204 49.28	15S.37E.15.143423	19910313 63.76

In addition, there is a monitor well installed in Section 11 to the southeast of the subject site where groundwater was measured to be 68.27' from the top of casing on April 7, 2005.

### VI. Work Performed

On April 25, 2005 Safety & Environmental Solutions, Inc. (SESI) installed 7 test trenches

inside the bermed area at the site. Test Trenches 1 - 4 were installed on the north end of the battery site to the following depths:

Test Trench # 1	7'
Test Trench # 2 and 3	5'
Test Trench # 4	4'

Test Trench # 5 was installed on the west side of the battery and excavated to a depth of 1' where an electric line was cut. This trench was abandoned at that time.

Test Trench # 6 was installed on the east side of the battery near the center and excavated to a depth of 8'.

Test Trench # 7 was installed on the southeast end of the battery and excavated to a depth of 3'. No sample was retrieved from this trench. White caliche was encountered at a depth of 3'.

Samples were taken from the bottom of each trench with the exception of trench # 5. The samples were properly packaged and transported under a chain of custody to Cardinal Laboratories in Hobbs, New Mexico for analysis. All samples were analyzed for Chlorides (EPA Method 4500-Cl<sup>-</sup>B) ,TPH (EPA Method 418.1) and BTEX (EPA Method SW-846-8260). The results of the analysis are presented below:

Date	Sample ID	CI <sup>-</sup>
4-26-05	TT 1 @ 7'	432
4-26-05	TT 2 @ 5'	416
4-26-05	TT 3 @ 5'	432
4-26-05	TT 4 @ 4'	96
4-26-05	TT 6 @ 8'	640

Date	Sample ID	ТРН	Benzene	Toluene	Ethyl Benzene	Total Xylene
4-27-05	TT 1 @ 7'	2040	<0.005	<0.005	<0.005	<0.015
4-27-05	TT 2 @ 5'	98.2	<0.005	<0.005	<0.005	<0.015
4-27-05	TT 3 @ 5'	1610	<0.005	<0.005	<0.005	<0.015
4-27-05	TT 4 @ 4'	10900	<0.005	<0.005	0.524	3.16
4-27-05	TT 6 @ 8'	3930	<0.005	<0.005	0.715	0.016

### VII. Conclusions

Based on the characterization of the site, the cleanup level reached by the application of the "Guidelines for Remediation of Leaks, Spills and Releases" New Mexico Oil Conservation Division (NMOCD) – August 13, 1993 (Guidelines) to this site is 1000 parts per million (ppm) Total Petroleum Hydrocarbons (TPH). Application of the New Mexico Oil Conservation Division's ranking criteria for contaminated soils at this site is presented below:

Depth to Ground Water:	10 points
Distance to Well Head or Water Source:	0 points
Distance to Surface Water/Waterways:	0 points
Total Score:	10 points

The results of the analyses indicate the hydrocarbon contamination to be above the NMOCD guidelines in Test Trenches 1, 3, 4 and 6. The chloride concentrations are slightly elevated but should not present a threat to groundwater.

# VIII. Figures & Appendices

Figure 1 - Vicinity Map Figure 2 - Site Plan Appendix A - C-141 Appendix B - Analytical Results Figure 1
Vicinity Map






Figure 2 Site Plan






**Merit Energy** 

State T Battery S2, T15S, R37E Lea County, New Mexico

Safety & Environmental Solutions, Inc.

# Appendix A Analytical Results





PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR SAFETY & ENVIRONMENTAL SOLUTIONS, INC. ATTN: BOB ALLEN 703 E. CLINTON, #102 HOBBS, NM 88240 FAX TO: (505) 393-4388

Receiving Date: 04/26/05 Reporting Date: 04/29/04 Project Number: MER-04-015 Project Name: STATE T Project Location: NOT GIVEN

Sampling Date: 04/25/05 Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: NF

Analyzed By: 8C/AH

LAB NUMBER	SAMPLE ID	TPH (mg/Kg)	Ci* (mg/Kg)	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DAT	E:	04/27/05	04/26/05	04/27/05	04/27/05	04/27/05	04/27/05
H9748-1	TT-1 7'	2040	432	<0.005	<0.005	<0.005	< 0.015
H9748-2	TT-2 5'	98.2	416	<0.005	<0.005	<0.005	<0.015
H9748-3	TT-3 5'	1610	432	<0.005	<0.005	<0.005	<0.015
H9748-4	TT-4 4'	10900	96	<0.005	< 0.005	0.524	3.16
H9748-5 TT-6 8'		3930	640	<0.005	<0.005	0.715	0.016
		~					
Quality Control		234	998	0.090	0.089	0.094	0.293
Truo Value QC		240	1000	0.100	0.100	0.100	0.300
% Recovery		97.6	99.8	89.8.	88.7	94.4	97.7
Relative Percent Difference		5.4	0,2	3.2	7.3	2.9	6.1

METHODS:

TRPHC-EPA 600/4-79-020 418.1;CI-Std. Methods 4500-Cl'B; BTEX-EPA SW-846 8260 \*Analyses performed on 1:4 wtv aqueous extracts.




# CHAIN-OF-CUSTODY AND ANALYSIS REQUEST


2111 Beechwood, Abliene, TX 79803 101 East Mariand, Hobbs, NM 88240 (916) 673-7001 Fax (915) 673-7020 (605) 393-2326 Fax (605) 393-2476													Page	d_	1_							
Company Name: SAFETY & ENVIRONMENTAL SOLUTIONS								BILL TO ANALYSIS REQUEST														
Project Manager:				·····					_	). ø:			,-									
Address: 703 E.CLINTON, #102									Company: SAME													
								Attn:														
Phone#: (5	05) 397-0510	Fax#: (505					8		Address:												[	
						State: Zip:																
Project Location:									Phone #:													
Sampler Name:									Fax #:										,			
FOR LABUSE ONLY			MATRIX					PRESERY. SAMPLING														
Lab I.D.  49748 - 1 - 3 - 4 - 5	Sample I.C TT-1 7' TT-2 5' TT-3 5' TT-4 48' TT-6 8'	).	GAN GIONAR OR COMP.	B CONTAINERS	SACUNDWATER		1 X X SOIL	35CATS .	OTHER:	Acidia Ac	K K K K ISE 1 COOL	OTHER:	DATE 4-25-05 11	1 ME 8:30 5:50 9:10 9:20 9:55	114/14 418,1	11/1/1 BTEX	11111 001					
						十	+-	1	$\Box$			-						<del>                                     </del>			·	
						十												<del>                                     </del>	· · · · · · · · · · · · · · · · · · ·			
		· · · · · · · · · · · · · · · · · · ·				$\top$	$\top$	-		_									,			
						7	$\top$	1												·		
LEASE BOTE: Labelty and improgra. Carcinal's lettery and court's notions recently for special and accounts made in the property of the second special property of the special																						
amese Hollnouis	196	Date:			a by		~	-		Pemi		0 com	14,	Phone Result		[] Yes		Но				
11-00 00	<i>b</i>	4-26-05	1	1										Fax Result		□ Yes	0	No.	<u> </u>		·	
Data: Ficeiver By: (Lab Stati)  Time:  Sample Condition Tenne, C totact By:												·	٠.							,		
Sampler - UPS - Bus - Other:						inti	#19}							,								

<sup>†</sup> Cardinal cannot accept verbal changes, Please fax written changes to (915) 673-7020.


Appendix B Site Photos



Backhoe excavating trench #1




Backhoe excavating trench # 1 foreground typical material on N. side of battery



Undisturbed material on N. Side of battery




N. side of battery




Test trench #1



Test trench # 1




Fest trench #2



Test trench #3




Test trench # 4




West side of 1,000 barrel tank




Test trenches # 3 (upper) & #4 (lower)




Test trenches # 1 (lower) & #2 (upper)




Test trenches #1 (lower) & #2 (upper)




Test trench #1 and surrounding area




Backhoe digging trench #2 (hit electric line here)



Test trench #4




Test trench #6




Test trench #6



Test trench #7




Test trench #7



Test trench # 7



Location of test trench # 6



Location of test trench #7 (behind water tank)