

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Linn Operating Inc.	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM 88240	Telephone No.	575-738-1739
Facility Name	CMU C #283	Facility Type	Injection
Surface Owner	State	Mineral Owner	API No. 30-025-34193

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	28	17S	33E	1033	South	1975	East	Lea

Latitude 32.8011717539685 Longitude -103.666034130641

NATURE OF RELEASE



Type of Release	Produced Water	Volume of Release	10 bbls	Volume Recovered	5bbls
Source of Release	Steel pipeline	Date and Hour of Occurrence	01/28/2015	Date and Hour of Discovery	01/28/2015 7:20am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* At appx 7:20am I received a phone call that I had an injection leak at CMU C#283. We got line shut in and dug down to find that it was leaking around the threads on the collar of the pipe. Line coming into injection well is a 2 3/8 steel plastic coated line. We stripped back one joint and replaced with fiber glass line.

Describe Area Affected and Cleanup Action Taken.* Appx 10bbls was spilled water ran about 192'ft from well head east to edge of location, and gathered just off location. The wind carried the mist east out in the pasture appx another 150' from the edge of location. Water misted out in the pasture on north side of location about 100' long and appx 110' wide. Clean up will be determined.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: E.L. Gonzales	Hydrologist	
Title: Production Supervisor	Approved by Environmental Specialist:	
E-mail Address: elgonzales@linenergy.com	Approval Date: 01/29/2015	Expiration Date: 03/29/2015
Date: 01/28/2015 Phone: 505-504-8002	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD	Attached <input type="checkbox"/> 3517

* Attach Additional Sheets If Necessary

guides. Submit final C-141 by
03/29/2015.

269324
nTO1502937249
pTO1502937440