

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chevron USA Inc.	Contact: James A. Trujillo
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No.: work: 575-704-3146 cell: 575-650-3602
Facility Name: VGSAU 148	Facility Type: Well
Surface Owner: New Mexico	Mineral Owner: New Mexico
API No. 3002530799	

LOCATION OF RELEASE

Unit Letter D	Section 1	Township 18S	Range 34E	Feet from the 1330	North Line	Feet from the 660	West Line	County Lea
------------------	--------------	-----------------	--------------	-----------------------	------------	----------------------	-----------	---------------

Closest well: Latitude Longitude -

NATURE OF RELEASE

Type of Release: Produced water release to land	Volume of Release: 153.75 BBLs	Volume Recovered: 30 BBLs
Source of Release: Fiberglass line failed	Date and Hour of Occurrence: 06/22/2015 09:30 AM	Date and Hour of Discovery: 06/22/2015 09:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? James A. Trujillo	Date and Hour: 06/22/2015 @ 5:26 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

By OCD District 1 at 2:43 pm, Jun 23, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


A spill of 153.75 BBLs of produced water was spilled to ground due to a fiberglass line failure.

Describe Area Affected and Cleanup Action Taken.*

The area affected was the VGSAU #148 and a vacuum truck was called out to vacuum up the spill. The next step is for backhoe to excavate top layer of soil approximate 12" deep and soil samples will be taken to the laboratory to determine TPH, Benzene and Chlorides contaminants levels. In case any of the contaminants levels are still high, the spill location will be turned over to Chevron management Company (EMC) for further remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:



Printed Name: James A. Trujillo

Title: HES Field Specialist


E-mail Address: jtgo@chevron.com

Date: 06/23/2015

Phone: 575-650-3602

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:



Approval Date: 06/23/2015

Expiration Date: 09/23/2015

Conditions of Approval:

Site samples required. Delineate and remediate as per MNOC guidelines. Geotag photographs of remediation required.

Attached ☐ 4323
1RP-3688

* Attach Additional Sheets If Necessary

nKJ1517453233
pKJ1517453689