

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: <i>Chevron</i>	Contact: Caleb Weaver
Address: <i>2401 Ave O Eunice, NM 88231</i>	Telephone No.: 432-235-9382
Facility Name: <i>Fred Turner #3 Battery</i>	Facility Type: Tank Battery

Surface Owner: SW Cattle Company	Mineral Owner:	API No.: 30-025-27589
----------------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter O	Section 6	Township 20	Range 38E	Feet from the 639 ft	North/South Line South	Feet from the 1448 ft	East/West Line East	County Lea
------------------	--------------	----------------	--------------	-------------------------	---------------------------	--------------------------	------------------------	---------------

Latitude: 32.596668 Longitude: -103.184024

NATURE OF RELEASE

Type of Release: <i>Oil, Produced water</i>	Volume of Release: Historical	Volume Recovered: N/A
Source of Release: <i>Tank</i>	Date and Hour of Occurrence: Historic	Date and Hour of Discovery: 5/1/15
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 1:49 pm, Aug 07, 2015

Describe Cause of Problem and Remedial Action Taken.*

Removed old tank from jobsite. Soil underneath the tank appears to be contaminated. Soil was removed from the area and disposed. Samples were taken every 4 ft, and a total of 8 ft was removed from the entire battery area. At 8 ft the samples yielded good results, and caliche and topsoil was brought back in and filled the hole. After, the area was seeded with BLM seed.

APPROVED

By OCD District 1 at 1:49 pm, Aug 07, 2015

Describe Area Affected and Cleanup Action Taken.*

Inside of a berm. Cleanup action was to haul contaminated soil to proper disposals and performed soil tests to ensure all affected soil was removed. Fresh dirt was brought in to fill back in the area, and the area was seeded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Caleb Weaver</i>		OIL CONSERVATION DIVISION	
Printed Name: Caleb Weaver		Approved by Environmental Specialist: <i>Janet Klyne</i>	
Title: Facilities Engineer		Approval Date: 08/07/2015	Expiration Date: ///
E-mail Address: Caleb.Weaver@chevron.com		Conditions of Approval:	
Date: 8/6/2015	Phone: 432-687-7258	Attached <input type="checkbox"/> IRP 3659	

* Attach Additional Sheets If Necessary