

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Linn Operating Inc.	Contact E.L. Gonzales
Address 2130 W Bender Blvd Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name CMU North Injection – (closest active well CMU #196)	Facility Type Water Station

Surface Owner State	Mineral Owner	API No. Closest well 30-025-32941
---------------------	---------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter H	Section 20	Township 17S	Range 33E	Feet from the 2473	North/South Line North	Feet from the 1259	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.820549 Longitude -103.6808777

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 168 bbls	Volume Recovered 0
Source of Release FG- Pipeline	Date and Hour of Occurrence 10/07/2015	Date and Hour of Discovery 10/07/2015 6:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
By JKeys at 8:59 am, Oct 13, 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* At approx. 6:30am leak was found, closet well was the CMU A #57. When I arrived water was spraying out of the ground towards the west. We got leak stopped and dug out and noticed a hole in the side of a fiberglass nipple.

Describe Area Affected and Cleanup Action Taken.* Leak was approx. 200' wide at the widest point, and approx. 500' long at the longest point. Leak sprayed out of ground towards west and ran downhill north, northeast. Approx. 168bbls spilled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: E.L. Gonzales	Approved by Environmental Specialist: 	
Title: Production Supervisor	Approval Date: 10/13/2015	Expiration Date: 12/13/2015
E-mail Address: elgonzales@linenergy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 3907
Date: 10/12/2015 Phone: 505-504-8002	Geotagged photos required.	

* Attach Additional Sheets If Necessary

pJXK1528632208
nJXK1528632099





