

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Matador Production Company	Contact Catherine Green	
Address 500 N Main St Ste One	Telephone No. 575-623-6601	
Facility Name Chevron 12 Fed # 5	Facility Type Oil Well	
Surface Owner	Mineral Owner	API No. 30-025-30682

LOCATION OF RELEASE

Unit Letter G	Section 12	Township 18S	Range 32E	Feet from the 1650	North/South Line FNL	Feet from the 1650	East/West Line FEL	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	---------------

Latitude 32.7646065 N Longitude -103.7166214 NAD83

NATURE OF RELEASE

Type of Release Oil	Volume of Release 35BBLs	Volume Recovered 25 BBLS
Source of Release Coupling on a pump failed.	Date and Hour of Occurrence Between 9/15/15 and 9/16/15	Date and Hour of Discovery Sept. 16, 2015 10:00 am
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Larry Brigrance, Production Foreman, Matador Resources	
By Whom? Ismael Lopez	Date and Hour Sept. 16, 2015 10:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <div>REVIEWED By Kellie Jones at 2:17 pm, Dec 08, 2015</div>		

Describe Cause of Problem and Remedial Action Taken.*
Coupling on a pump failed. Fluid contained in dike. Hauler recovered 25 bbls of fluid.

Describe Area Affected and Cleanup Action Taken.*
Inside dike. Hauler recovered 25 bbls of fluid. Diamondback Disposal will be on location to collect soil samples, and complete reclamation work. Lab reports and photos will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Catherine Green		OIL CONSERVATION DIVISION	
Printed Name: Catherine Green		Approved by Environmental Specialist:	
Title: Regulatory Analyst		Approval Date:	
E-mail Address: cgreen@matadorresources.com		Conditions of Approval:	
Date: Nov. 20, 2015 Phone: 575-623-6601		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Chevron 12 Fed #5 Final Report

Dec. 7, 2015

Matador Resources Production Foreman encountered a broken coupling on a transfer pump on Sept. 16, 2015 at 10:00am. It was estimated that 35 barrels of fluid had spilled into the earthen dike. See attached photos. The foreman turned the well off, telephoned to report the spill, telephoned for a vacuum truck to vacuum up as much fluid as possible, and ordered a new pump. 25 barrels of fluid were recovered.

The well was drilled in 1989. Based on the location of the well, depth to ground water is an estimate from data obtained from the NM Office of the State Engineer. It is estimated that depth to ground water is between 100 and 400 feet from the surface.

Diamondback Disposal Service collected soil samples at the indicated locations. See attached location plat diagram. Soil samples were sent to Cardinal Labs. Original soil samples from the surface indicated benzene, toluene, and total BTEX to be above reporting limits. Contaminated soil was removed from the spill area and taken to R360 environmental. A second set of soil samples were collected at a depth of 18 inches below surface. Cardinal Labs analyzed them. See attached. Results are below reporting limits. Clean soil was brought in, and the location was returned to normal operations.



Pictures of spill, September 16, 2015





September 28, 2015

BRANDON PRICE
DIAMONDBACK DISPOSAL SERVICE INC.
P. O. BOX 2491
HOBBS, NM 88241

RE: CHEVRON 12 #5 BATTERY

Enclosed are the results of analyses for samples received by the laboratory on 09/22/15 13:38.

Cardinal Laboratories is accredited through Texas NELAP under certificate number T104704398-13-5. Accreditation applies to drinking water, non-potable water and solid and chemical materials. All accredited analytes are denoted by an asterisk (*). For a complete list of accredited analytes and matrices visit the TCEQ website at www.tceq.texas.gov/field/ga/lab_accred_certif.html.

Cardinal Laboratories is accredited through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Halocetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V1, V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,



Celely D. Keene
Lab Director/Quality Manager

Analytical Results For:

 DIAMONDBACK DISPOSAL SERVICE INC.
 BRANDON PRICE
 P. O. BOX 2491
 HOBBBS NM, 88241
 Fax To: (575) 392-9376

Received:	09/22/2015	Sampling Date:	09/21/2015
Reported:	09/28/2015	Sampling Type:	Soil
Project Name:	CHEVRON 12 #5 BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Judy Garcia
Project Location:	NOT GIVEN		

Sample ID: SURFACE INITIAL #1 (H502495-01)

BTEX 80218		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	6.30	0.200	09/25/2015	ND	2.01	100	2.00	0.972	
Toluene*	8.58	0.200	09/25/2015	ND	1.72	86.1	2.00	2.19	
Ethylbenzene*	3.97	0.200	09/25/2015	ND	1.62	80.8	2.00	3.25	
Total Xylenes*	4.06	0.600	09/25/2015	ND	5.09	84.9	6.00	1.94	
Total BTEX	22.9	1.20	09/25/2015	ND					

Surrogate: 4-Bromofluorobenzene (P10) 94.1 % 85.6-137

Chloride, SM4500Cl-B		mg/kg		Analyzed By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	336	16.0	09/23/2015	ND	432	108	400	0.00	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	204	100	09/24/2015	ND	178	88.8	200	12.4	
DRO >C10-C28	31600	100	09/24/2015	ND	226	113	200	0.764	

Surrogate: 1-Chlorooctane 105 % 47.2-157

Surrogate: 1-Chlorooctadecane 1050 % 52.1-176

Cardinal Laboratories

* = Accredited Analyte

H5025-1075: Liability and Damages. Cardinal's liability and checks include records for any data entry, whether based in context or not, and be linked to the amount paid by client for analysis. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruption, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or licensees arising out of or related to the performance of the services described by Cardinal, regardless of whether such claim is based upon any of the aforementioned reasons or otherwise. Results shall only be those as they appear on the report. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Analytical Results For:

 DIAMONDBACK DISPOSAL SERVICE INC.
 BRANDON PRICE
 P. O. BOX 2491
 HOBBS NM, 88241
 Fax To: (575) 392-9376

Received:	09/22/2015	Sampling Date:	09/21/2015
Reported:	09/28/2015	Sampling Type:	Soil
Project Name:	CHEVRON 12 #5 BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Judy Garcia
Project Location:	NOT GIVEN		

Sample ID: SURFACE INITIAL #2 (H502495-02)

BTEX 80218		mg/kg		Analyzed By: MS						
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier	
Benzene*	1.68	0.050	09/25/2015	ND	2.01	100	2.00	0.972		
Toluene*	3.87	0.050	09/25/2015	ND	1.72	86.1	2.00	2.19		
Ethylbenzene*	2.91	0.050	09/25/2015	ND	1.62	80.8	2.00	3.25		
Total Xylenes*	3.32	0.150	09/25/2015	ND	5.09	84.9	6.00	1.94		
Total BTEX	11.8	0.300	09/25/2015	ND						

Surrogate: 4-Bromofluorobenzene (PIL) 115 % 85.6-137

Chloride, SM4500Cl-B			mg/kg							Analyzed By: HM	
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier		
Chloride	256	16.0	09/23/2015	ND	432	108	400	0.00			

TPH 8015M			mg/kg							Analyzed By: MS	
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier		
GRO C6-C10	108	100	09/24/2015	ND	178	88.8	200	12.4			
DRO >C10-C28	22500	100	09/24/2015	ND	226	113	200	0.764			

Surrogate: 1-Chlorooctane 104 % 47.2-157

Surrogate: 1-Chlorooctadecane 760 % 52.1-176

Cardinal Laboratories

* = Accredited Analyte

LIMITED WARRANTY: Cardinal Laboratories and its affiliates warrant that the analytical results reported herein were obtained using the methods and procedures described in the report. Cardinal Laboratories and its affiliates warrant that the analytical results reported herein were obtained using the methods and procedures described in the report. Cardinal Laboratories and its affiliates warrant that the analytical results reported herein were obtained using the methods and procedures described in the report.



CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

101 East Marland, Hobbs, NM 88240
(875) 393-2326 FAX (875) 393-2478

Company Name: Dimondback Drywall Service

Project Manager: Dimondback Drywall Service

Address: PO Box 2491

City: Hobbs State: NM Zip: 88241

Phone #: 575-392-4994 Fax #: 575-392-9376

Project #: 1147-doe

Project Name: Cleburn 12 #5 BHTCY

Project Location: Albuquerque, NM

Sampler Name: Albuquerque Police

Sampler ID: 1147-doe

Sample ID: 1147-doe

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

BILL TO

P.O. #: 1147-doe

Company: Dimondback

Address: PO Box 2491

City: Hobbs State: NM Zip: 88241

Phone #: 575-392-4994 Fax #: 575-392-9376

Project #: 1147-doe

Project Name: Cleburn 12 #5 BHTCY

Project Location: Albuquerque, NM

Sampler Name: Albuquerque Police

Sampler ID: 1147-doe

Sample ID: 1147-doe

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

Substrate: Soil

ANALYSIS REQUEST

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Analysis Request: CI

Analysis Request: TPH

Analysis Request: BTEX

Received By: Dimondback

Date: 11/15/15

Time: 10:58

Signature: Dimondback

Printed Name: Dimondback

Address: PO Box 2491

City: Hobbs State: NM Zip: 88241

Phone #: 575-392-4994 Fax #: 575-392-9376

Project #: 1147-doe

1. Cardinal cannot accept verbal changes. Please fax written changes to 800-445-2676



New water transfer pump.
Chevron 12-5



Soil samples collected and analyzed by Cardinal
Labs. Final results below. New transfer pump.



November 06, 2015

BRANDON PRICE

DIAMONDBACK DISPOSAL SERVICE INC.

P. O. BOX 2491

HOBBS, NM 88241

RE: CHEVRON 12 #5 BATTERY

Enclosed are the results of analyses for samples received by the laboratory on 11/02/15 9:05.

Cardinal Laboratories is accredited through Texas NELAP under certificate number T104704398-13-5. Accreditation applies to drinking water, non-potable water and solid and chemical materials. All accredited analytes are denoted by an asterisk (*). For a complete list of accredited analytes and matrices visit the TCEQ website at www.tceq.texas.gov/field/qa/lab_accred_certif.html.

Cardinal Laboratories is accredited through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Haloacetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V1, V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,



Celley D. Keene

Lab Director/Quality Manager

Final lab results from Cardinal
Labs for Chevron 12 -5 spill.

Analytical Results For:

 DIAMONDBACK DISPOSAL SERVICE INC.
 BRANDON PRICE
 P. O. BOX 2491
 HOBBS NM, 88241
 Fax To: (575) 392-9376

Received:	11/02/2015	Sampling Date:	10/27/2015
Reported:	11/06/2015	Sampling Type:	Soil
Project Name:	CHEVRON 12 #5 BATTERY	Sampling Conditions:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	EDDY COUNTY		

Sample ID: EAST CONFIRMATION (H502870-01)

BTEX 80218		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	11/05/2015	ND	2.08	104	2.00	2.22	
Toluene*	<0.050	0.050	11/05/2015	ND	2.28	114	2.00	2.94	
Ethylbenzene*	<0.050	0.050	11/05/2015	ND	2.06	103	2.00	3.69	
Total Xylenes*	<0.150	0.150	11/05/2015	ND	6.56	109	6.00	3.57	
Total BTEX	<0.300	0.300	11/05/2015	ND					

Surrogate: 4-Bromofluorobenzene (PIL) 107 % 73.6-140

Chloride, SM4500Cl-B		mg/kg		Analyzed By: AP					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	11/04/2015	ND	416	104	400	0.00	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	11/04/2015	ND	212	106	200	1.40	
DRO >C10-C28	<10.0	10.0	11/04/2015	ND	218	109	200	2.41	

Surrogate: 1-Chlorooctane 117 % 35-147

Surrogate: 1-Chlorooctadecane 130 % 28-171

Analytical Results For:

 DIAMONDBACK DISPOSAL SERVICE INC.
 BRANDON PRICE
 P. O. BOX 2491
 HOBBS NM, 88241
 Fax To: (575) 392-9376

Received:	11/02/2015	Sampling Date:	10/27/2015
Reported:	11/06/2015	Sampling Type:	Soil
Project Name:	CHEVRON 12 #5 BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	EDDY COUNTY		

Sample ID: WEST CONFIRMATION (H502870-02)

BTX 8021B		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	11/05/2015	ND	2.08	104	2.00	2.22	
Toluene*	<0.050	0.050	11/05/2015	ND	2.28	114	2.00	2.94	
Ethylbenzene*	<0.050	0.050	11/05/2015	ND	2.06	103	2.00	3.69	
Total Xylenes*	<0.150	0.150	11/05/2015	ND	6.56	109	6.00	3.57	
Total BTX	<0.300	0.300	11/05/2015	ND					

Surrogate: 4-Bromofluorobenzene (PIL) 107 % 73.6-140

Chloride, SM4500Cl-B		mg/kg		Analyzed By: AP						
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier	
Chloride	<16.0	16.0	11/04/2015	ND	416	104	400	0.00		

TPH 8015M		mg/kg		Analyzed By: MS						
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier	
GRO C6-C10	<10.0	10.0	11/04/2015	ND	212	106	200	1.40		
DRO >C10-C28	<10.0	10.0	11/04/2015	ND	218	109	200	2.41		

Surrogate: 1-Chlorooctane 112 % 35-147

Surrogate: 1-Chlorooctadecane 122 % 28-171

Analytical Results For:

 DIAMONDBACK DISPOSAL SERVICE INC.
 BRANDON PRICE
 P. O. BOX 2491
 HOBBS NM, 88241
 Fax To: (575) 392-9376

Received:	11/02/2015	Sampling Date:	10/27/2015
Reported:	11/06/2015	Sampling Type:	Soil
Project Name:	CHEVRON 12 #5 BATTERY	Sampling Conditions:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	EDDY COUNTY		

Sample ID: CENTER CONFIRMATION (H502870-03)

BTX 80218		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	11/05/2015	ND	2.08	104	2.00	2.22	
Toluene*	<0.050	0.050	11/05/2015	ND	2.28	114	2.00	2.94	
Ethylbenzene*	<0.050	0.050	11/05/2015	ND	2.06	103	2.00	3.69	
Total Xylenes*	<0.150	0.150	11/05/2015	ND	6.56	109	6.00	3.57	
Total BTX	<0.300	0.300	11/05/2015	ND					

Surrogate: 4-Bromofluorobenzene (PIL) 108 % 73.6-140

Chloride, SM4500Cl-B		mg/kg		Analyzed By: AP					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	11/04/2015	ND	416	104	400	0.00	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C5-C10	<10.0	10.0	11/04/2015	ND	212	106	200	1.40	
DRO >C10-C28	<10.0	10.0	11/04/2015	ND	218	109	200	2.41	

Surrogate: 1-Chlorooctane 110 % 35-147

Surrogate: 1-Chlorooctadecane 121 % 28-171



CHAIN-OF-CUSTODY AND ANALYSIS REQ


101 East Marland Hobbs, NM 88240
(575) 383-2326 FAX (575) 383-2478

Company Name: Dimondale, Alaska, Inc		P.O. #:		BILL TO		ANALYSIS REQUEST											
Project Manager: Barbara Rice		Company:															
Address: PO Box 2491		Attn: CMPLC															
City: Hobbs		State: NM		Zip: 88241													
Phone #: 575-392-9996		Fax #: 575-392-9376															
Project #: 12		Project Owner: Matthew															
Project Name: Chuvon 12 Fed #5		City: Albuquerque		State: NM		Zip: 87102											
Project Location: Edgy County		Phone #:															
Sampler Name: Barbara Rice		Fax #:															
FOR LAB USE ONLY		PRESERVE		SAMPLING													
Lab I.D.	Sample I.D.	(GRAB OR C/COMP)	CONTAINERS	GROUNDWATER	WASTEWATER	SOIL	OIL	SLUDGE	OTHER	ACID/BASE	ICE / COOL	OTHER	DATE	TIME	TPH	BTEX	CI
150287D	First confirmation												11-23-15	10:12	Y	Y	Y
3	2nd confirmation												11-23-15	10:29	Y	Y	Y
3	3rd confirmation												11-23-15	10:19	Y	Y	Y
REMARKS: Received By: Allen Hunsaker																	
Delivered By: (Circle One) UPS 5:58																	
Sample Condition: Good																	
Fax #: 575-383-2478																	

Diamondback Location Plat

Well/Facility Name: Chuvon 12 #5

Date: 11-30-15



Approx 18 in deep

Topographic map of the Heyco, New Mexico area. The map shows elevation contours, roads, and a highlighted area labeled "HEYCO Chevron Federal 12" #5". The map includes a grid with coordinates and various elevation points.

Key features on the map include:

- HEYCO Chevron Federal "12" #5**: A large, dark, irregularly shaped area in the center-right of the map, likely representing a federal land acquisition or a specific geological feature.
- HEYCO**: A label in the center-left of the map, above the "Chevron Federal" area.
- ROCKY MOUNTAIN**: A label in the bottom-left corner, indicating the location of the Rocky Mountains.
- GRID COORDINATES**: A grid system is overlaid on the map, with coordinates ranging from 118 to 122 on the horizontal axis and 3850 to 3950 on the vertical axis.
- ELEVATION POINTS**: Numerous elevation points are marked with numbers, such as 3857, 3853, 3851, 3850, 3849, 3845, 3844, 3843, 3842, 3841, 3840, 3839, 3838, 3837, 3836, 3835, 3834, 3833, 3832, 3831, 3830, 3829, 3828, 3827, 3826, 3825, 3824, 3823, 3822, 3821, 3820, 3819, 3818, 3817, 3816, 3815, 3814, 3813, 3812, 3811, 3810, 3809, 3808, 3807, 3806, 3805, 3804, 3803, 3802, 3801, 3800, 3799, 3798, 3797, 3796, 3795, 3794, 3793, 3792, 3791, 3790, 3789, 3788, 3787, 3786, 3785, 3784, 3783, 3782, 3781, 3780, 3779, 3778, 3777, 3776, 3775, 3774, 3773, 3772, 3771, 3770, 3769, 3768, 3767, 3766, 3765, 3764, 3763, 3762, 3761, 3760, 3759, 3758, 3757, 3756, 3755, 3754, 3753, 3752, 3751, 3750, 3749, 3748, 3747, 3746, 3745, 3744, 3743, 3742, 3741, 3740, 3739, 3738, 3737, 3736, 3735, 3734, 3733, 3732, 3731, 3730, 3729, 3728, 3727, 3726, 3725, 3724, 3723, 3722, 3721, 3720, 3719, 3718, 3717, 3716, 3715, 3714, 3713, 3712, 3711, 3710, 3709, 3708, 3707, 3706, 3705, 3704, 3703, 3702, 3701, 3700, 3699, 3698, 3697, 3696, 3695, 3694, 3693, 3692, 3691, 3690, 3689, 3688, 3687, 3686, 3685, 3684, 3683, 3682, 3681, 3680, 3679, 3678, 3677, 3676, 3675, 3674, 3673, 3672, 3671, 3670, 3669, 3668, 3667, 3666, 3665, 3664, 3663, 3662, 3661, 3660, 3659, 3658, 3657, 3656, 3655, 3654, 3653, 3652, 3651, 3650, 3649, 3648, 3647, 3646, 3645, 3644, 3643, 3642, 3641, 3640, 3639, 3638, 3637, 3636, 3635, 3634, 3633, 3632, 3631, 3630, 3629, 3628, 3627, 3626, 3625, 3624, 3623, 3622, 3621, 3620, 3619, 3618, 3617, 3616, 3615, 3614, 3613, 3612, 3611, 3610, 3609, 3608, 3607, 3606, 3605, 3604, 3603, 3602, 3601, 3600, 3599, 3598, 3597, 3596, 3595, 3594, 3593, 3592, 3591, 3590, 3589, 3588, 3587, 3586, 3585, 3584, 3583, 3582, 3581, 3580, 3579, 3578, 3577, 3576, 3575, 3574, 3573, 3572, 3571, 3570, 3569, 3568, 3567, 3566, 3565, 3564, 3563, 3562, 3561, 3560, 3559, 3558, 3557, 3556, 3555, 3554, 3553, 3552, 3551, 3550, 3549, 3548, 3547, 3546, 3545, 3544, 3543, 3542, 3541, 3540, 3539, 3538, 3537, 3536, 3535, 3534, 3533, 3532, 3531, 3530, 3529, 3528, 3527, 3526, 3525, 3524, 3523, 3522, 3521, 3520, 3519, 3518, 3517, 3516, 3515, 3514, 3513, 3512, 3511, 3510, 3509, 3508, 3507, 3506, 3505, 3504, 3503, 3502, 3501, 3500, 3499, 3498, 3497, 3496, 3495, 3494, 3493, 3492, 3491, 3490, 3489, 3488, 3487, 3486, 3485, 3484, 3483, 3482, 3481, 3480, 3479, 3478, 3477, 3476, 3475, 3474, 3473, 3472, 3471, 3470, 3469, 3468, 3467, 3466, 3465, 3464, 3463, 3462, 3461, 3460, 3459, 3458, 3457, 3456, 3455, 3454, 3453, 3452, 3451, 3450, 3449, 3448, 3447, 3446, 3445, 3444, 3443, 3442, 3441, 3440, 3439, 3438, 3437, 3436, 3435, 3434, 3433, 3432, 3431, 3430, 3429, 3428, 3427, 3426, 3425, 3424, 3423, 3422, 3421, 3420, 3419, 3418, 3417, 3416, 3415, 3414, 3413, 3412, 3411, 3410, 3409, 3408, 3407, 3406, 3405, 3404, 3403, 3402, 3401, 3400, 3399, 3398, 3397, 3396, 3395, 3394, 3393, 3392, 3391, 3390, 3389, 3388, 3387, 3386, 3385, 3384, 3383, 3382, 3381, 3380, 3379, 3378, 3377, 3376, 3375, 3374, 3373, 3372, 3371, 3370, 3369, 3368, 3367, 3366, 3365, 3364, 3363, 3362, 3361, 3360, 3359, 3358, 3357, 3356, 3355, 3354, 3353, 3352, 3351, 3350, 3349, 3348, 3347, 3346, 3345, 3344, 3343, 3342, 3341, 3340, 3339, 3338, 3337, 3336, 3335, 3334, 3333, 3332, 3331, 3330, 3329, 3328, 3327, 3326, 3325, 3324, 3323, 3322, 3321, 3320, 3319, 3318, 3317, 3316, 3315, 3314, 3313, 3312, 3311, 3310, 3309, 3308, 3307, 3306, 3305, 3304, 3303, 3302, 3301, 3300, 3299, 3298, 3297, 3296, 3295, 3294, 3293, 3292, 3291, 3290, 3289, 3288, 3287, 3286, 3285, 3284, 3283, 3282, 3281, 3280, 3279, 3278, 3277, 3276, 3275, 3274, 3273, 3272, 3271, 3270, 3269, 3268, 3267, 3266, 3265, 3264, 3263, 3262, 3261, 3260, 3259, 3258, 3257, 3256, 3255, 3254, 3253, 3252, 3251, 3250, 3249, 3248, 3247, 3246, 3245, 3244, 3243, 3242, 3241, 3240, 3239, 3238, 3237, 3236, 3235, 3234, 3233, 3232, 3231, 3230, 3229, 3228, 3227, 3226, 3225, 3224, 3223, 3222, 3221, 32

CONTOUR INTERVAL 10'

OPERATOR Harvey E. Yates Company
LEASE Chevron Federal "12" #5.
U.S.G.S. TOPOGRAPHIC MAP
Dog Lake, NM

**JOHN WEST ENGINEERING
HOBBS, NEW MEXICO
(505) 393-3117**