District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in

Form C-141

Revised August 8, 2011

## Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Name of Company: Devon Energy Production Co LP Jeff Heath, Devon Asst. Completions Foreman Contact: (6137)Address: PO Box 250, Artesia, NM 88211 Telephone No. 575-513-2274 Facility Name: Black Mamba 15 State Com 9H Facility Type: Two-track road north of oil well Surface Owner: State & Federal Mineral Owner: State ^ Federal API No. 30-025-42631 LOCATION OF RELEASE Unit Letter East/West Line Section Township Range Feet from the North/South Line Feet from the County 0 26 **22S** 33E 22 South 2365 East Lea Latitude: 32.35651 Longitude: -103.54121 NATURE OF RELEASE Volume of Release: 30 bbls Type of Release: Produced Water Volume Recovered: 1 bbl Source of Release: Date and Hour of Occurrence Date and Hour of Discovery Water line coupling 12/13/2015, 4:15 PM 12/13/2015, 4:15 PM Was Immediate Notice Given? If YES, To Whom? OCD-Kellie Jones **BLM-Jim Amos** By Whom? Date and Hour: OCD: 12/13/2015, 6:12 PM BLM: 12/15/2015, 2:55 PM Jeff Heath, Devon Asst. Completions Foreman If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? Yes No RECEIVED If a Watercourse was Impacted, Describe Fully.\* By Kellie Jones at 9:22 am, Dec 23, 2015 Describe Cause of Problem and Remedial Action Taken.\* The 8 inch cam lock on a 10 inch victaulic booster fitting broke on a produced water line resulting in the release of an estimated 30 barrels of produced water on the pipeline's 2-track road. Line pinchers were applied to stop the flow. These broken fittings were replaced and this water line was put back into operation. Describe Area Affected and Cleanup Action Taken.\* A spill of 30 barrels of produced water occurred approximately 2 1/2 miles north of the Black Mamba 15 State Com 9H off of pad on a 2-track pipeline easement. The spill is approximately 33,826 square feet following the pipeline easement with the estimated center point of the spill being Latitude 32.35651 and Longitude -103.54121, running southwest and northeast. Due to sandy road access, the produced water soaked into the ground and a vacuum truck that could get to the spill was not found until the next day on 12/14/15 and they were able to recover an estimated 1 barrel of produced water from the sandy area. An environmental company has been called to test and create a remediation plan for submittal. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Denise Menoud 02/23/2016 Approval Date: 12/23/2015 **Expiration Date:** Title: Field Admin Support E-mail Address: Denise.Menoud@dvn.com Conditions of Approval: Attached Site samples required. Delineate and remediate 1RP-4059 Date: 12/16/2015 Phone: 575-746-5544 as per MNOCD guides. Geotag photographs of







