APPROVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Me By Kellie Jones at 7:48 am, Jan 13, 2016

Energy Minerals and Natural Resources

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

	1		Rele	ase Notific	ation	and Co	rrective A	ction				
						OPERA'	ΓOR		nitial Report	\boxtimes	Final	Report
Name of Co (6137)	ompany:	Devon Ener	gy Produ	uction Co LP	(Contact:	Brian	Kuh				
Address:		PO Box 250				Telephone No. 575- 616-1540						
Facility Nar	ne:	Rattlesnake	13-12 Fe	ed Com 1H	I	Facility Type: 0.1 miles south of location						
Surface Owner: Federal Mineral Owner						Federal			API No. 30-025-40912			
LOCATION OF RELEASE												
Unit Letter P				Feet from the 330		South Line South	Feet from the 330	East/West Li East				
Latitude: 32.036958 Longitude: 103.416218												
NATURE OF RELEASE												
Type of Rele	ase: P	roduced Wat	er				Release: 25 bb		ne Recovered	: 17 bbl	S	
Source of Release: Lay Flat Water Transfer Line						6/13/15, 3:00 PM 6/13/15				ur of Discovery 15, 3:00 PM		
Was Immedi	ate Notice (Yes [No Not Re	If YES, To	Whom? CD-Mike Brate	her	BLM-Jim A	mos			
By Whom? Brian Kuh, Devon Foreman						Date and Hour: 6/13/2015, 4:00 PM						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*						REVIEWED						
Describe Cause of Problem and Remedial Action Taken.* N/A By Kellie Jones at 7:48 am, Jan 13, 2016												
Two punctures in the treated water transfer line approximately one foot apart caused the leak. Immediately, the crew pinched the line and utilized absorption pads, a vacuum truck, preventive flow devices, and a tele-handler wheel path to contain the spill and recover all but 1 barrel.												
Describe Area Affected and Cleanup Action Taken.* 3.5 feet x 20 feet off location and not contained. Talon will take soil samples and prepare a remediation plan.												
The impacted area was excavated to a depth of 4 feet deep and a 20 mil liner was installed in the bottom of the excavation. All of the excavated material was hauled to Lea Land, LLC, an approved disposal facility. The excavated areas were backfilled with new sand, re-contoured to match the surrounding area and seeded with the recommended BLM seed mixture for the area.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: Denise Mensud						OIL CONSERVATION DIVISION						
Printed Name: Denise Menoud						Approved by Environmental Specialist:						
Title: Field Admin Support						Approval Da	te: 01/13/2016	Expira	Expiration Date: //			
E-mail Address: Denise.Menoud@dvn.com						Conditions of Approval: Ensure BLM approval. Attached IRR 3699						
Date: 1/11	/2015	r	hone: 575	-746-5544		1RP-3689						

^{*} Attach Additional Sheets If Necessary