

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Red Tank 35 Federal #3 SWD Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-33149

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	35	22S	32E					Lea

Latitude N 32.34700° Longitude W 103.65068°

#### NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 700 bbls of produced water	Volume Recovered	672 bbls produced water
Source of Release	2" ball valve flew off water tank 3	Date and Hour of Occurrence	01/18/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	01/18/2016 @ 10:05 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

**RECEIVED**

**By Kellie Jones at 7:14 am, Jan 27, 2016**

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A 2" ball valve blew off of water tank 3 spilling 700 bbls of produced water onto the ground and spraying 2 bbls of oil. A vacuum truck recovered 672 bbls of produced water and the valve was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 180' x 200' on location. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Casey Summers	Approved by Environmental Specialist: 		
Title: NM Environmental Advisor	Approval Date: 01/27/2016	Expiration Date: 03/27/2016	
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.		Attached <input type="checkbox"/> IRP-4118
Date: 1/26/16	Phone: (575) 513-8289		

\* Attach Additional Sheets If Necessary

nKJ1602726266  
pKJ1602726419