District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

## Energy Minerals and Natural

State of New Mexi By JKeyes at 3:20 pm, Aug 22, 2016

**RECEIVED** 

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19,15,29 NMAC.

## **Release Notification and Corrective Action**

						OPERA'	<u>ror</u>		🛛 Initia	al Report		Final Report
Name of Co		Oxy Permia			Contact Casey Summers							
Address 6 Desta Drive, Midland, TX 79705						Telephone No. (575) 513-8289						
Facility Name Runner 2 Fed Com #1 Battery						Facility Type Battery						
Surface Owner BLM Mineral Owner						API No. 30-025-40095						
Transfer Owner						ALTINO. JU-U2J-4007J						
_				LOCA	ATIO:	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/V	West Line County			
.,	,	225	32E									
H	2	22S						Lea County.	, NM			
			I	Latitude <u>N 32.4</u>	2297°	Longitu	de W 103.6380	6°				
				NAT	TIDE	OF DEL	FACE					
Type of Release Produced water mixed with rain water Volume of Release 160 bbls Volume Recovered 120 bbls produced												
Type of Release Produced water mixed with rain water						Volume of Release 160 bots			water mixed with rain water			
Source of Release Corrosion of a 2" steel flow line						Date and Hour of Occurrence			Date and Hour of Discovery			
						08/10/2016						
Was Immediate Notice Given?   ☑ Yes ☐ No ☐ Not Required						If YES, To Whom?						
				NO I NOT K	equirea							
By Whom? Kathy@ BBC International, Inc.						Date and Hour 08/10/2016 @ 4:24 pm						
Was a Watercourse Reached?  ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
Corrosion of a 2" steel flow line caused a leak of 160 bbls of produced water. A vacuum truck recovered 120 bbls of a produced water and rain mixture												
and the line w			d a leak o	i too obis oi piou	ucea w	ater. A vacuu	in truck recovered	1 1 20 DD	as or a proc	auceu water a	ao rai	n mixture
Describe Area	Affected	and Cleanup A	Action Tak	en.*								
The effected :	•	!1 661	1001		ale e este :	D			,	*.1	12.00	,
approved by t				orth of location in	the pit	area. Remedi	ation will be comp	pietea in	accordano	e with a reme	diatic	on pian
upproved by c			21.7									
							knowledge and u					
							nd perform correc					
public health	or the envi	priment. The	acceptano	e of a C-141 repo	ort by th	ie NMOCD m	arked as "Final Roon that pose a thro	eport" de	oes not reli	eve the opera	tor of	liability
or the environ	perations p iment. In h	ave raneu to a	idequalety ICD accer	investigate and r	emediai report d	le contaminati loes not reliev	on that pose a thr e the operator of i	eat to gr responsi	ouna water bility for c	r, suriace wate	ar, nui Th' an s	man neattn
federal, state,					торонго	1003 1101 141141	e the operator or t	caponai	onny tot c	omphiance wit	11 1111	other
						OIL CONSERVATION				DIVISION		
Signature:	M	_		Anneand by Environmental Specialist								
Printed Name: Casey Summers						Approved by Environmental Specialist:						
							09/22/2014	_		10/22/20	016	
Title: NM Environmental Advisor						Approval Date: 08/22/2016   Expiration Date: 10/22/2016						
<b>-</b>	_											
E-mail Address: Casey Summers@oxy.com						Conditions of Discrete sample	i <b>Approval:</b> es only. Delineate	and ren	nediate per	Attached 1RP 4411		
Date: X = 2.2 - (a Phone: (575) 513-8289						VMOCD guidelines. Ensure BLM concurrence/						
Attach Addit	ional Shee	ets If Necess		(070) 010-02	a	<del>pproval.</del>				pJXK162355		
										r,		