

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

By JKeyes at 11:19 am, Aug 29, 2016

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Energy Transfer Co. Field Services	Contact: Johnnie Bradford
Address: 600 N. Marienfeld Street	Telephone No. (432) 250-5542 (cell) (817) 302-9812 (off)
Facility Name: Keystone Lateral 16"	"Facility Type: Pipeline
Surface Owner: New Mexico	Mineral Owner: _____ API No. _____

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	26	25S	37E	593.9	North	536.4	West	Lea

Latitude 32°5'46' N Longitude 103°7'55' W

NATURE OF RELEASE

Type of Release: Condensate	Volume of Release: 13.6 bbls	Volume Recovered: 0
Source of Release:	Date and Hour of Occurrence: 08/22/2016	Date and Hour of Discovery: 08/22/2016 08:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

A Watercourse was not impacted.

Describe Cause of Problem and Remedial Action Taken.*

The hammer cap on the Willis block valve was loose. The Willis valve began to leak when the pipeline filled up with liquid due to the forced isolation of this section of pipeline several miles downstream of the valve to repair a leak on the pipeline. The hammer cap was immediately tightened upon discovery to prevent additional liquid from escaping the vent.

Describe Area Affected and Cleanup Action Taken.*

The affected area starts at the north of the pipe riser and extends to the South East for approximately 144'. Area will be remediated to NMOCD Recommended Remediation Action Levels (RRALs) by removing contaminated soil and back filling with uncontaminated soil following confirmation sampling. Contaminated soil will be disposed at an NMOCD approved landfill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford	Approved by Environmental Specialist: 	
Title: Sr. Environmental Specialist	Approval Date: 08/29/2016	Expiration Date: 10/29/2016
E-mail Address: johnnie.bradford@energytransfer.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 4421
Date: 08/24/2016 Phone: (432) 250-5542		

* Attach Additional Sheets If Necessary

nJXK1624240297
pJXK1624240411