Good morning Mr. Burton:

In one aggregated document, please send 1) the laboratory results from September 1, 2017 for 1RP-3419 in electronic format; 2) mark the locations of the soil samples and outline of the release area on a scaled map; 3) a summary of the remedial activities completed and the concerns noted in the email dated July 5, 2017 addressed.

Thanks, Olivia

From: Mike Burton [mailto:marineburton@gmail.com]
Sent: Thursday, October 12, 2017 3:25 PM
To: Arias, Arthur <aaarias@blm.gov>; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Aaron Hickert <ahickert@linnenergy.com>; Rickman, Rick <rrickman@linnenergy.com>; Butters, Thomas <tbutters@linnenergy.com>; Paul Cowan <pcowan75@me.com>
Subject: Topaz 19 Fed #1 downsize

All,

Attached is a google earth image with the proposed downsize area marked in blue. The red line is a DCP underground utility. Thank you for your time.

Michael Ray Burton 575-499-5306 USMC VET C&M Services