Office _	State of New Mexico	Form C-103
Dietrict I (575) 303-6161 En	nergy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 HOBBS	OCCONSERVATION DIVISION 1220 South St. Francis Dr.	WELL API NO. 30-025-30282
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210	IL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 MAR 0.7 2	/D46	STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 11 2 2 District IV – (505) 476-3460	2013 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505 KECEN SUNDRY NOTICES AN	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO	DRILL OR TO DEEPEN OR PLUG BACK TO A	/
DIFFERENT RESERVOIR. USE "APPLICATION F PROPOSALS.)	FOR PERMIT" (FORM C-101) FOR SUCH	Hightower A
1. Type of Well: Oil Well X Gas Well	☐ Other	8. Well Number 1
2. Name of Operator Lawson Operating, L.	LC ,	9. OGRID Number
	-: /	270358
3. Address of Operator		10. Pool name or Wildcat
P O Box 52667, Midland, TX 79710		KNOWLES;DRINKARD, WEST
4. Well Location		
Unit Letter_A:571_feet fro		
Section 4	Township 17S Range 371	
11. El	evation (Show whether DR, RKB, RT, GR, et	<i>C.</i>)
12 Check Annron	riate Box to Indicate Nature of Notice	Report or Other Data
12. Check Appropr	rate Box to indicate induce of induce	z, report of Other Data
NOTICE OF INTENT	i i	BSEQUENT REPORT OF:
1	AND ABANDON REMEDIAL WO	
· · · · · · · · · · · · · · · · · · ·		RILLING OPNS. P AND A
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE	IPLE COMPL	NI JOB
DOWNINGLE COMMINGLE		
OTHER:	☐ OTHER:	
13 Describe proposed or completed one	amatiana (Clasely, stata all mantinant datails	and give pertinent dates, including estimated date
	E RULE 19.15.7.14 NMAC. For Multiple C	
of starting any proposed work). SE proposed completion or recompletion	E RULE 19.15.7.14 NMAC. For Multiple Con.	
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment	
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450'	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval from 2-5/6-13 Test tubing in hole. Set page	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new p	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval from 2-5/6-13 Test tubing in hole. Set page	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450'	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set page 2-6-13 Acidize new Drinkard perfora	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new p	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set page 2-6-13 Acidize new Drinkard perfora	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new p	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set page 2-6-13 Acidize new Drinkard perfora	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new p	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set page 2-6-13 Acidize new Drinkard perfora	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new p	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set page 2-6-13 Acidize new Drinkard perfora	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new p	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set page 2-6-13 Acidize new Drinkard perfora	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new p	ompletions: Attach wellbore diagram of
of starting any proposed work). SE proposed completion or recompletion. 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval from 2-6-13 Test tubing in hole. Set past 2-6-13 Acidize new Drinkard perforation. 2-8-13 Return well to production.	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new prations with 5000 gallons 15% NEFE HCl	ompletions: Attach wellbore diagram of perforations
of starting any proposed work). SE proposed completion or recompletion. 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval from 2-5/6-13 Test tubing in hole. Set pass 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production.	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new prations with 5000 gallons 15% NEFE HCl	ompletions: Attach wellbore diagram of perforations
of starting any proposed work). SE proposed completion or recompletion. 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval from 2-6-13 Test tubing in hole. Set past 2-6-13 Acidize new Drinkard perforation. 2-8-13 Return well to production.	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new prations with 5000 gallons 15% NEFE HCl	ompletions: Attach wellbore diagram of perforations
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set past 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production Spud Date: February 4, 2013	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new prations with 5000 gallons 15% NEFE HCl Rig Release Date:	completions: Attach wellbore diagram of operforations
of starting any proposed work). SE proposed completion or recompletion. 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval from 2-6-13 Test tubing in hole. Set past 2-6-13 Acidize new Drinkard perforation. 2-8-13 Return well to production.	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new prations with 5000 gallons 15% NEFE HCl Rig Release Date:	completions: Attach wellbore diagram of operforations
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set past 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production Spud Date: February 4, 2013	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new parations with 5000 gallons 15% NEFE HCl Rig Release Date: February true and complete to the best of my knowled	perforations 11, 2013 Ige and belief.
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set past 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production Spud Date: February 4, 2013	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new prations with 5000 gallons 15% NEFE HCl Rig Release Date:	completions: Attach wellbore diagram of operforations
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set pas 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production Spud Date: February 4, 2013 I hereby certify that the information above is	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new parations with 5000 gallons 15% NEFE HCl Rig Release Date: February true and complete to the best of my knowled TITLE Manager	perforations 11, 2013 Ige and belief. DATE March 5, 2013
of starting any proposed work). SE proposed completion or recompletic 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set pas 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production Spud Date: February 4, 2013 I hereby certify that the information above is SIGNATURE Type or print name Phillip Layson	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new parations with 5000 gallons 15% NEFE HCl Rig Release Date: February true and complete to the best of my knowled	perforations 11, 2013 Ige and belief. DATE March 5, 2013
of starting any proposed work). SE proposed completion or recompletion 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set past 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production Spud Date: February 4, 2013 I hereby certify that the information above is SIGNATURE Type or print name Phillip Lawson For State Use Only	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new prations with 5000 gallons 15% NEFE HCl Rig Release Date: February true and complete to the best of my knowled TITLE Manager E-mail address: pllawson@aol	DATE March 5, 2013 DATE March 5, 2013 PHONE: 432-556-0797
of starting any proposed work). SE proposed completion or recompletic 2-4-13 Pull out of hole with product 2-5-13 Perforate Drinkard interval f 2-5/6-13 Test tubing in hole. Set pas 2-6-13 Acidize new Drinkard perfor 2-8-13 Return well to production Spud Date: February 4, 2013 I hereby certify that the information above is SIGNATURE Type or print name Phillip Layson	E RULE 19.15.7.14 NMAC. For Multiple Con. tion equipment from 8400'-8450' cker between existing perforations and new parations with 5000 gallons 15% NEFE HCl Rig Release Date: February true and complete to the best of my knowled TITLE Manager	perforations 11, 2013 Ige and belief. DATE March 5, 2013

MAR 3 3 2013

Mun