

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
JUN 17 2013 RECEIVED

WELL API NO. 30-025-07961
5. Indicate Type of Lease STATE [] FEE [X]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name East Hobbs San Andres Unit
8. Well Number 910
9. OGRID Number 269324
10. Pool name or Wildcat Hobbs; San Andres, East
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3610

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [X] Gas Well [] Other []
2. Name of Operator Linn Operating, Inc.
3. Address of Operator 600 Travis, Ste. 5100, Houston, Texas 77002
4. Well Location Unit Letter A : 330 feet from the N line and 330 feet from the E line
Section 31 Township 18S Range 39E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3610

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON [X]
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1. MIRU plugging equipment. ND wellhead and NU BOP.
2. RIH and tag RBP @ 4350. Circulate hole w/ mud laden fluid. Spot 25 sx cement on top of plug 4350-4110.
3. POH w/ tbg. Perf 5 1/2 @ 2935 & Sqz. 45 sx cement. Displace to 2835. WOC & Tag. (Btm of salt)
4. Perf 5 1/2 @ 1930 & Sqz 55 sx cement. Displace to 1780. WOC & Tag. (Top of salt and shoe)
5. Perf 5 1/2 @ 300 & Sqz 100 sx to surface.
6. Cut off well head and weld on Dry Hole Marker.

Spud Date: []

Rig Release Date: []

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry Callahan TITLE Reg Compliance III DATE 6/14/2013
Type or print name Terry Callahan E-mail address: tcallahan@linnenergy.com PHONE: 2818404272

APPROVED BY: Mary Brown TITLE Compliance Officer DATE 6/28/2013
Conditions of Approval (if any)

