BUR Do not use this t abandoned well.	EAU OF LAND MANAGEME OTICES AND REPORTS O Form for proposals to drill of Use Form 3160-3 (APD) for T IN TRIPLICATE – Other instruction	NT NELLS N WELLS of to re-enter an such proposals.	FC The Scheme of Scheme o	Tribe Name
2. Name of Operator Ridgeway Arizona Oil Corp			9. API Well No. 30-041-10445	
3a. Address         3b. Phone No. (include area code)           200 N. Loraine, STE 1440         432-687-0303			10. Field and Pool or Exploratory Area Chaveroo, San Andres	
4. Location of Well Footage, Sec., T., R., M., or Survey Description) 600 FSL & 660 FEL Sec. 27, T07S, R33E			11. County or Parish, State Roosevelt, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA				
TYPE OF SUBMISSION          Image: Constraint of the second seco	Alter Casing	Fracture Treat Recla New Construction Recon Plug and Abandon Temp	ION Iction (Start/Resume) mation nplete orarily Abandon Disposal	Water Shut-Off Well Integrity Other Workover
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)				
<ul> <li>Re-enter subject well and cleanout to PBTD; conduct an MIT, re-stimulate the San Andres P1/P2, and RTP. Slimhole completion as necessary. [5-1/2"]</li> <li>MIRU WO rig.</li> <li>Pull existing completion</li> <li>Make clean out run with bit and BHA to PBTD @ 4387 ft.</li> <li>Set packer above top perforation. Test casing to 500 psi/30 mins. Chart if successful.</li> <li>Stimulate P1/P2.</li> <li>Swab back stimulation volumes.</li> <li>If casing test fails MIT; run slimhole completion.</li> <li>Run rods. Re-start pumping unit and return to production.</li> </ul>				
14. Thereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Jana True Signature		Title Regulatory/Productio	on Manager	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by /S/ DAVID Conditions of approval, if any, are attached. Please Contact The BLM Roswe Hours Prior To The Scheduled ( For Wells In Chaves And Roose Office Hours Or After Office Ho Engineer On Call During Office Or After Office Hours Call (575)	Approval of this notice to ware which Approval of this notice to ware which Il Field Office At Least 24 Casing Integrity Test. velt County, During urs Call (575) 627-0205. Hours Call (575) 627-0275	PETROLEUM E	Date <b>LL</b> FIELD CEFICE make to any department or	AUG 0 8 2013 agency of the United States any false, 5 1 5 2013

/