HOBBS OCD					``	
HOBBS OCC NOV 1 3 2013 Form 3160-5 (March 2012)	New Mexico Oli Conservation Division Likevie I 1625 N. Frencis Port Port I					
Form 3160-5	UNITED STATE	25		FURNER DIVISION DIVISION DIVISION DIVISION DIVISION DIVISION DIVISION DIVISION DI DIVISION DI DIVISIONI DI DIVISIO DI DIVISIO DI DIVISIONI DI DIVISIONI DI DIVISIONI DI DIVISIONI DI DIVISIONI DI DIVISIONI DI DIVISI DI DIVISIONI DI DIVISIONI DI DIVISI DI DIVISIONI DI		
	DEPARTMENT OF THE	INTERIOR	#Service-	CX	OMB No. 1004-0137 spires: October 31, 2014	
RECE	BUREAU OF LAND MAN	IAGEMENT		5. Lease Serial No. NMNM0117529		
	Y NOTICES AND REPO		20	6. If Indian, Allottee of	r Tribe Name	
	II. Use Form 3160-3 (A					
	BMIT IN TRIPLICATE – Other	instructions on page 2.		7. If Unit of CA/Agree	ment, Name and/or No.	
1. Type of Well Oil Well I Oil Well	ias Well 🔲 Other			8. Well Name and No.	/	
2. Name of Operator				Federal 21 #3 9. API Well No. 30-041-10515	/	
Ridgeway Arizona Oil Corp. 3a. Address		3b. Phone No. (include area	code)	10. Field and Pool or E	xploratory Area	
200 N. Loraine, STE 1440 Midland, TX 79701	/	432-242-4544		Chaveroo, San Andr		
4. Location of Well (Footage, Sec. 660 FSL & 1980 FEL Sec. 21, T. 07S, R. 33E	, T.,R.,M., or Survey Description,)		11. County or Parish, S Roosevelt Co., NM	itate	
12. C	HECK THE APPROPRIATE BO	X(ES) TO INDICATE NATU	IRE OF NOTIO	CE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION			LADE OF ACT	ION		
Notice of Intent	Acidize	Deepen		uction (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat		amation mplete	Well Integrity Other	
Subsequent Report	Change Plans	Plug and Abandon		oorarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back		r Disposal		
In response to WO # 13OT01Wo Ridgeway Arizona Oil Corp (Rid well bore diagram.		lug and abandon Federal 2	1 #3 accordin	g to the attached prop	osed plugging procedure and	
Ridgeway or a representative of	Ridgeway will contact BLM 24	hours prior to beginning pl	ugging proce	dures.		
		APPR	OVED FC	DR_ <u>3_</u> MONT	H PERIOD	
		ENDIN	P m •	3 0 6 2014		
4. I hereby certify that the foregoing	is true and correct. Name (Printed	I/Typed)				
Jana True	Title Production/Regulatory Mgr					
	Date 10/25/2013					
<u>A</u> uoo	THIS SPACE I	FOR FEDERAL OR S	TATE OFF			
Approved by /S/ DAVI	D R. GLASS	PET Title	ROLEUME		NOV 0 6 2013	
Conditions of approval, if any, are attached to the applicant holds legal or equitabentitle the applicant to conduct operation	ched. Approval of this notice does to be title to those rights in the subject	not warrant or certify	ROSW	ELL FIELD CFFK		
		crime for any person knowingly	and willfully to	make to any department	or agency of the United States any false,	
fictitious or fraudulent statements of the	epresentations as to any matter with					
		L MAB/oc	14 און או ט	10013	10V 1 4 13×	

Ridgeway Arizona Oil Corporation

St. Johns Helium/CO₂ Project

Plugging Procedure Federal 21 #3 API No. – 30-041-10515 O-21-O7S-33E 660 FSL 1980 FEL

- 1. Prepare location and test anchors
- 2. MIRU plugging rig
- 3. Notify OCD/BLM 24 hours prior to commencement of P & A procedure.
- 4. NDWH/NU BOP
- 5. RIH w-4 ½ CIBP on 2 3/8 WS @ 4100' (+/-) within 100' of top perf 4165'
 - a. Spot 35' of cement on CIBP
 - b. WOC bump plug @ 4065' (+/-)
- 6. Load well with a minimum of 9 lb. mud and conduct MIT to 500 psi. , test for leak off.
 - a. Bleed pressure off after MIT.
- 7. MIRU WL and RIH w/perf gun to 2500'
 - a. perforate @ 2 JSPF
 - b. POOH w/WL
 - c. RDWL
- 8. TIH w/WS Squeeze 75 SX cement plug @ 2500' to 2300'
 - a. Wait on cement
 - b. Tag plug @ 2300' or above
 - MIRU WL and RIH w/perf gun to 1900'
 - a. perforate @ 2 JSPF
 - b. POOH w/WL
 - c. RDWL

9.

- 10. TIH w/WS Squeeze 60 SX cement plug @ 1900' to 1750'
 - a. 7" csng. Shoe @ 1810'
 - b. Wait on cement
 - c. Tag plug @ 1750' or above
- 11. MIRU WL and RIH w/perf gun to 60'
 - a. perforate @ 2 JSPF
 - b. POOH w/WL
 - c. RDWL
- 12. TIH w/WS Circulate cement plug from 60' to surface
 - a. Wait on cement
 - b. Cut off well head
- 13. RDMO Plugging Rig
 - a. Install P & A marker plate
 - b. Cut off dead men
 - c. Remediate Location

Co. Rep	0	
Well Name	Federal 21	Well No. 3
Field	Chaveroo	
County	Roosevelt	
State	NM	
Date	1/0/1900	
Date Comp		·
кв	0.00	·

Perf @ 60' circ. To surf.

7" to 1810'

Perf @ 1900' Sqz. 60 sx

Perf @ 2500' Sqz. 75 sx

-~

Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	7	0	20#	1810	375	Surface
Inter Csg	0	0	0	0	0	0
Prod Csg	4 1/2	0	9 1/2	4373	350	0
Liner O.D.	_0	0	0	0	0	0

Failure Analysis

Lease rederaizi Well # 3 redu Chaveroo Well Test Data BOPD MCF	Well Test Data BOPD BWPD MCF Unit Name & Size 9 Perforations 4165-4291 TBG Data Pump Size Strokes Per. Min. Stroke Length Seat Nipple Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.		Lease Federal 21 Well # 3 Field Chaveroo
Unit Name & Size Perforations 4165-4291 TBG Data Pump Size Strokes Per. Min. Stroke Length Seat Nipple Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	Unit Name & Size 4165-4291 Perforations 4165-4291 TBG Data [Pump Size] Strokes Per. Min. Stroke Length Seat Nipple Tension Rod Grade Taper 3 Taper 4 Predicitive Load	ŀ I	Lease Federal 21 Well # 3 Field Chaveroo
Perforations 4165-4291 TBG Data Pump Size Strokes Per. Min. Stroke Length Seat Nipple Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	Perforations 4165-4291 TBG Data [Pump Size] Strokes Per. Min. Stroke Length Seat Nipple Tension [Rod String Taper 1] Taper 2 TAC [Rod Grade] Taper 3] Taper 4 Predicitive Load [Actual Load] [LiST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS. [Actual Load] [Actual Load]		
TBG Data Pump Size Strokes Per. Min. Stroke Length Seat Nipple Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	TBG Data Pump Size Strokes Per. Min. Stroke Length Seat Nipple Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.		
Strokes Per. Min. Stroke Length Seat Nipple Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	Strokes Per. Min. Stroke Length Seat Nipple Tension IRods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load IActual Load List DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.		
Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load IST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS. Image: Comparison of the second sec	Tension Rods String Taper 1 Taper 2 TAC Rod Grade Taper 3 Taper 4 Predicitive Load	f	Strokes Per Min Stroke Length Seat Ninnle
TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load Itaper 4 LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	TAC Rod Grade Taper 3 Taper 4 Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	5 A	Tension Rode String Tager 1 Tager 2
Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	Predicitive Load Actual Load LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	A.A.	
LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	LIST DATES, REASON FOR FAILURES & MEASURES TAKEN TP PREVENT SAID FAILURES & NON FAILURE PULLS.	2	
FAILURES & NON FAILURE PULLS.	FAILURES & NON FAILURE PULLS.	14 I.	
		. 1	FAILURES & NON FAILURE PULLS.
		K.	
		L >	
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY		
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY		
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY		
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY	ł	
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY		
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY		
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY	-	
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY		
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY	l	
	LIST ANY RECOMMENDATIONS TO PREVENT FUTURE FAILURES OR ANY		
COMMENTS ON WELL CONDITIONS THAT WILL CONTRIBUTE TO FAILURES.		1	
COMMENTS ON WELL CONDITIONS THAT WILL CONTRIBUTE TO FAILURES.			
COMMENTS ON WELL CONDITIONS THAT WILL CONTRIBUTE TO FAILURES.			

Perforations 4165, 70, 83, 89, 4223, 25, 28, 30, 40, 43, 46, 54, 56, 58, 61, 65, 70, 76, 83, 86, 4291

35' cmt@ 4065' CIBP @ 4100'

. .:

PBTD @	4349	
TD @	4373	

ETD @ ____ 0

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety** (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office (RFO), prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.

2. <u>Notification</u>: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

6. <u>Monument</u>: Upon abandonment of the well, all casing shall be cut-off at the base of the cellar or 3-feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¹/₄ inch thick and welded in place. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Timing Limitation Lease Stipulation / Condition of Approval For Lesser Prairie-Chicken:</u> Oil and gas activities including 3-D geophysical exploration, and drilling will not be allowed in lesser prairie-chicken habitat during the period from March 1 through June 15 annually. During that period, other activities that produce noise or involve human activity, such as the maintenance of oil and gas facilities, geophysical exploration other than 3-D seismic operations, and pipeline, road, and well pad construction, will be allowed except between 3:00 am and 9:00 am. The 3:00 am to 9:00 am restriction will not apply to normal, around-the-clock operations, such as venting, flaring, or pumping, which do not require a human presence during this period. Additionally, no new drilling will be allowed within up to 200 meters of leks known at the time of permitting. Normal vehicle use on existing roads will not be restricted. Exhaust noise from pump jack engines must be muffled or otherwise controlled so as not to exceed 75 db measured at 30 feet from the source of the noise.

8. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.