(April 2004)	DEPARTMEN	ED STATES T OF THE INTER	LIOR	Hobbs		FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
		AND MANAGEME			5. Lease Seria	No.
	NDRY NOTICES A use this form for p				NM-086 6. If Indian,	Allottee or Tribe Name
	ned well. Use Form					
	IN TRIPLICATE- C	Other instruction	s on rever	98880CD	7. If Unit or	CA/Agreement, Name and/or N
1. Type of Well ✔ Oil Well□	Gas Well	Other	МДү	<u>212014</u>	8. Well Nan	
2. Name of Operator Armstrong Energy Corporation					Superior Federal #5 9. API Well No.	
3a. Address	ox 1973, Roswell, NM 882	3b. Pho 202-1973 575-	one No. (include) 625-2222	OErvel	30-025-	
··· · · · · · · · · · · · · · · · · ·	аде, Sec., T., R., M., or Survey				10. Field and Pearl Q	d Pool, or Exploratory Area
Unit M 990'	FSL & 400' FWL, Sec 25	T198_B34F			11. County	or Parish, State
	15L & 400 F W L, 5tt 25	, 1170- NJ4 L			Lea Co	unty, New Mexico
12. CHE	ECK APPROPRIATE E	BOX(ES) TO INDIC	ATE NATUR	E OF NOTICE,	REPORT, OR	OTHER DATA
TYPE OF SUBMISSI	·····		TYF	PE OF ACTION		
Notice of Intent	Acidize		pen ture Treat	Production (Start/Resume)	Water Shut-Off
Subsequent Report		· _ · · · ·	Construction	Recomplete		Other
Final Abandonment N	Notice Convert to		and Abandon Back	Water Dispo		
If the proposal is to de Attach the Bond unde following completion testing has been comp	er which the work will be per n of the involved operations.	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only	bsurface locatio and No. on file v a multiple comp	ns and measured and with BLM/BIA. Rec pletion or recompletion	I true vertical depti uired subsequent on in a new interva- lamation, have bee	hs of all pertinent markers and ze reports shall be filed within 30 d al, a Form 3160-4 shall be filed o en completed, and the operator h RECLAMATION PROCED
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the sit 1. Contact BLM 2. MI RU, ND V 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Win WOC 4 hrs, t 6. POH, RU Win	teepen directionally or recomp er which the work will be per n of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. o 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug. ireline and perf 4 shots @	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) ag any plugging opera roduction tbg. apg mud. Spot 25 sx c) 1,990'. TIH w/ tbg a	ubsurface locatio ond No. on file v a multiple comp a fler all require tions. (Lea Co ement on top on nd pump 75 sy	ns and measured and with BLM/BIA. Req pletion or recompletion ments, including rec punty Wells: 575- of CIBP. Pull up x Class "C" w/ 2%	l true vertical depti uired subsequent n on in a new interva lamation, have bed 393-3612) to 3,175', spot 2: 6 CaCl plug, dis	hs of all pertinent markers and ze reports shall be filed within 30 d al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the sit 1. Contact BLM 2. MI RU, ND W 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Win WOC 4 hrs, t 6. POH, RU Win to Surface for 7. Cut off WH a 8. Install ground 9. Notify author	teepen directionally or recomp er which the work will be per n of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. o 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug.	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) ag any plugging opera roduction tbg. opg mud. Spot 25 sx c) 1,990'. TIH w/ tbg and y 291'. TIH w/ tbg and w G.L. release rig. Upon ap and and location, re-se	a multiple comp a multiple comp a fler all require tions. (Lea Co ement on top o nd pump 75 sx o proval, RD and red.	ns and measured and with BLM/BIA. Req pletion or recompletion ments, including rec bunty Wells: 575- of CIBP. Pull up 1 x Class "C" w/ 2% Class "C" plug, ci d move out.	l true vertical depti juired subsequent i on in a new interva lamation, have bed 393-3612) to 3,175', spot 2: 6 CaCl plug, dis rc annular volu SEE AT	hs of all pertinent markers and ze reports shall be filed within 30 de al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs splace to 1,870'. PUH,
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. Contact BLM 2. MI RU, ND V 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Wir WOC 4 hrs, t 6. POH, RU Wir to Surface for 7. Cut off WH a 8. Install ground 9. Notify author 10. Clean location	teepen directionally or recomp er which the work will be per 1 of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. 0 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug. ireline and perf 4 shots @ r full 291' surface plug. and mast anchors 3' below d level Dry Hole marker. rized BLM officer before on, remove caliche, rip ro	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) g any plugging opera roduction tbg. opg mud. Spot 25 sx c a 1,990'. TIH w/ tbg a b 291'. TIH w/ tbg and w G.L. release rig. Upon ap rod and location, re-se	a multiple comp a multiple comp a fler all require tions. (Lea Co ement on top o nd pump 75 sx o proval, RD and red.	ns and measured and with BLM/BIA. Req pletion or recompletion ments, including rec bunty Wells: 575- of CIBP. Pull up 1 x Class "C" w/ 2% Class "C" plug, ci d move out.	l true vertical depti juired subsequent i on in a new interva lamation, have bed 393-3612) to 3,175', spot 2: 6 CaCl plug, dis rc annular volu SEE AT	hs of all pertinent markers and zz reports shall be filed within 30 di al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs splace to 1,870'. PUH, me to Surface and fill 5.5'' of TACHED FOR TIONS OF APPF
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. Contact BLM 2. MI RU, ND V 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Win WOC 4 hrs, t 6. POH, RU Win to Surface for 7. Cut off WH a 8. Install ground 9. Notify author 10. Clean location F <u>CCPUAL</u> (Lat 14. I hereby certify tha Name (Printed/Ty	teepen directionally or recomp er which the work will be per n of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. o 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug. ireline and perf 4 shots @ r full 291' surface plug. and mast anchors 3' below d level Dry Hole marker. rized BLM officer before on, remove caliche, rip ro <u>pe [Dry La [</u> at the foregoing is true and <i>yped</i>]	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) g any plugging opera roduction tbg. opg mud. Spot 25 sx c a 1,990'. TIH w/ tbg a b 291'. TIH w/ tbg and w G.L. release rig. Upon ap rod and location, re-se	bisurface locatio ond No. on file v a multiple comp a filer all require tions. (Lea Co ement on top of nd pump 75 sx d pump 75 sx of proval, RD and red.	ns and measured and with BLM/BIA. Req pletion or recompletion ments, including rec punty Wells: 575- of CIBP. Pull up 1 x Class "C" w/ 2% Class "C" plug, ci d move out.	l true vertical depti uired subsequent on in a new interva lamation, have bed 393-3612) to 3,175', spot 2: 6 CaCl plug, dis rc annular volu SEE AT CONDI	hs of all pertinent markers and zz reports shall be filed within 30 di al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs splace to 1,870'. PUH, me to Surface and fill 5.5'' of TACHED FOR TIONS OF APPF
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. Contact BLM 2. MI RU, ND V 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Win WOC 4 hrs, t 6. POH, RU Win to Surface for 7. Cut off WH a 8. Install ground 9. Notify author 10. Clean location	teepen directionally or recomp er which the work will be per n of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. o 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug. ireline and perf 4 shots @ r full 291' surface plug. and mast anchors 3' below d level Dry Hole marker. rized BLM officer before on, remove caliche, rip ro <u>pe [Dry La [</u> at the foregoing is true and <i>yped</i>]	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) g any plugging opera roduction tbg. opg mud. Spot 25 sx c a 1,990'. TIH w/ tbg a b 291'. TIH w/ tbg and w G.L. release rig. Upon ap rod and location, re-se	bisurface locatio ond No. on file v a multiple comp a filer all require tions. (Lea Co ement on top of nd pump 75 sx d pump 75 sx of proval, RD and red.	ns and measured and with BLM/BIA. Req pletion or recompletion ments, including rec bunty Wells: 575- of CIBP. Pull up 1 x Class "C" w/ 2% Class "C" plug, ci d move out.	l true vertical depti uired subsequent on in a new interva lamation, have bed 393-3612) to 3,175', spot 2: 6 CaCl plug, dis rc annular volu SEE AT CONDI	hs of all pertinent markers and zz reports shall be filed within 30 di al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs splace to 1,870'. PUH, me to Surface and fill 5.5'' of TACHED FOR TIONS OF APPF
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. Contact BLM 2. MI RU, ND V 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Win WOC 4 hrs, t 6. POH, RU Win to Surface for 7. Cut off WH a 8. Install ground 9. Notify author 10. Clean location F CCPURC (MC) 14. I hereby certify tha Name (Printed/Ty	eepen directionally or recomp er which the work will be per n of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. o 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug. ireline and perf 4 shots @ r full 291' surface plug. and mast anchors 3' below id level Dry Hole marker. rized BLM officer before on, remove caliche, rip ro <u>2c D D D D</u>	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) ag any plugging opera roduction tbg. apg mud. Spot 25 sx c and 1,990'. TIH w/ tbg and a 291'. TIH w/ tbg and a 291'. TIH w/ tbg and a 291'. TIH w/ tbg and a 201 correct	bisurface locatio ond No. on file v a multiple comp a fler all require tions. (Lea Co ement on top on nd pump 75 sy d pump 75 sy	ns and measured and with BLM/BIA. Req pletion or recompletion ments, including rec ounty Wells: 575- of CIBP. Pull up 1 x Class "C" w/ 2% Class "C" plug, ci d move out. <u>Field Engineer</u> 04/18/2014	l true vertical depti uired subsequent n on in a new interva lamation, have bed 393-3612) to 3,175', spot 2: 6 CaCl plug, dis rc annular volu SEE AT CONDI	hs of all pertinent markers and zz reports shall be filed within 30 di al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs splace to 1,870'. PUH, me to Surface and fill 5.5'' of TACHED FOR TIONS OF APPF
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si 1. Contact BLM 2. MI RU, ND V 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Wir WOC 4 hrs, t 6. POH, RU Wir to Surface for 7. Cut off WH a 8. Install ground 9. Notify author 10. Clean location F. Geourd (ex) 14. Ihereby certify tha Name (<i>Printed/T</i>) Kyle Alp	eepen directionally or recomp er which the work will be per n of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. o 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug. ireline and perf 4 shots @ r full 291' surface plug. and mast anchors 3' below id level Dry Hole marker. rized BLM officer before on, remove caliche, rip ro <u>2c D D D D</u>	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) g any plugging opera roduction tbg. opg mud. Spot 25 sx c a 1,990'. TIH w/ tbg a b 291'. TIH w/ tbg and w G.L. release rig. Upon ap rod and location, re-se	ibsurface locatio ond No. on file v a multiple comp a file all require tions. (Lea Co ement on top on nd pump 75 sy d pump	ns and measured and with BLM/BIA. Rec pletion or recompletion ments, including rec ounty Wells: 575- of CIBP. Pull up x Class "C" w/ 2% Class "C" plug, ci d move out. <u>CLA, LPC</u> Field Engineer 04/18/2014	I true vertical depti uired subsequent on in a new interva- lamation, have bee 393-3612) to 3,175', spot 2: 5 CaCl plug, dis rc annular volu SEE AT CONDI	hs of all pertinent markers and zz reports shall be filed within 30 di al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs replace to 1,870'. PUH, me to Surface and fill 5.5" of TACHED FOR TIONS OF APPF
If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the sit 1. Contact BLM 2. MI RU, ND V 3. RU Wireline : 4. TIH w/ tbg to tag plug. 5. POH, RU Win WOC 4 hrs, t 6. POH, RU Win to Surface for 7. Cut off WH a 8. Install ground 9. Notify author 10. Clean location 14. I hereby certify tha Name (<i>Printed/T</i>) Kyle All Signature	teepen directionally or recomp er which the work will be per n of the involved operations. I pleted. Final Abandonment N ite is ready for final inspection 4 24 hrs prior to beginnin WH, NU BOP, POH w/ pr and set CIBP @ 4,850'. o 4,850', circ hole w/ 9.2 p ireline and perf 4 shots @ tag plug. ireline and perf 4 shots @ r full 291' surface plug. and mast anchors 3' below id level Dry Hole marker. rized BLM officer before on, remove caliche, rip ro <u>2 c D D D D</u> itthe foregoing is true and <i>'yped</i>)	plete horizontally, give su formed or provide the Bo If the operation results in Notices shall be filed only n.) ag any plugging opera roduction tbg. and Spot 25 sx c and Spot	ibsurface locatio ond No. on file v a multiple comp a fler all require tions. (Lea Co ement on top on nd pump 75 sy d pump	ns and measured and with BLM/BIA. Req pletion or recompletion ments, including rec ounty Wells: 575- of CIBP. Pull up 1 x Class "C" w/ 2% Class "C" plug, ci d move out. <u>Field Engineer</u> 04/18/2014	I true vertical depti uired subsequent on in a new interva- lamation, have bee 393-3612) to 3,175', spot 2: 5 CaCl plug, dis rc annular volu SEE AT CONDI	hs of all pertinent markers and zz reports shall be filed within 30 di al, a Form 3160-4 shall be filed of en completed, and the operator h RECLAMATION PROCED ATTACHED 5 sx plug. PUH, WOC 4 hrs splace to 1,870'. PUH, me to Surface and fill 5.5'' of TACHED FOR TIONS OF APPF

,

Armstrong Energy Corporation P.O. Box 1973 Roswell, NM 88202-1973

Well: Superior Federal #5




P&A Procedures

- Contact BLM office 24 hours prior to beginning any plugging operations. (Lea County Wells 575-393-3612)
- 2. MI RU, ND W.H., NU BOP, POOH with production tubing.
- 3. Rig up W.L. and set CIBP @ 4,850'.
- 4. TIH w/tbg to 4,850', circulate hole w/ 9.2ppg mud. Spot 25 sx cement on top of CIBP. Pull up to 3,175', spot 25 sx plug. PUH, WOC 4 hrs, tag plug
- 5. POOH, rig up wireline and perforate 4 shots @ 1,990'. TIH w/tbg and pump 75 sx Class "C" w2% CaCl plug, displace to 1,870'. PUH, WOC 4 hrs, tag plug
- 6. POOH, rig up wireline and perforate 4 shots @ 291'. TIH w/tbg and pump 75 sx Class "C" plug, circulate annular volume to surface and fill 5.5" casing to surface for full 291' surface plug.
- 7. Cut off WH & mast anchors 3' below G.L.
- 8. Install ground level dry hole marker,
- 9. Notify authorized BLM officer before release rig, upon approval RDMO
- 10. Clean location, remove caliche, rip road and location, reseed.







BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet, a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Timing Limitation Stipulation / Condition of Approval for lesser prairie-chicken: Oil and gas activities including 3-D geophysical exploration, and drilling will not be allowed in lesser prairie-chicken habitat during the period from March 1st through June 15th annually. During that period, other activities that produce noise or involve human activity, such as the maintenance of oil and gas facilities, pipeline, road, and well pad construction, will be allowed except between 3:00 am and 9:00 am. The 3:00 am to 9:00 am restriction will not apply to normal, around-the-clock operations, such as venting, flaring, or pumping, which do not require a human presence during this period. Additionally, no new drilling will be allowed within up to 200 meters of leks known at the time of permitting. Normal vehicle use on existing roads will not be restricted. Exhaust noise from pump jack engines must be muffled or otherwise controlled so as not to exceed 75 db measured at 30 feet from the source of the noise.

<u>Ground-level Abandoned Well Marker to avoid raptor perching</u>: Upon the plugging and subsequent abandonment of the well, the well marker will be installed at ground level on a plate containing the pertinent information for the plugged well. For more installation details, contact the Carlsbad Field Office at 575-234-5972.

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¹/₄ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name
 - b. Second row: Well name and number
 - c. Third row: Legal location to include ¼¼, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¼¼ (example: 1980 FNL 1980 FWL) being on the top row.
 - d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Interim Reclamation Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses.

Interim reclamation consists of minimizing the footprint of disturbance by reclaiming all portions of the well site not needed for production operations. The portions of the cleared well site not needed for operational and safety purposes are recontoured to a final or intermediate contour that blends with the surrounding topography as much as possible. Sufficient level area remains for setup of a workover rig and to park equipment. Topsoil is respread over areas not needed for all-weather operations. In order to inspect and operate the well or complete workover operations, it may be necessary to drive, park, and operate on restored, interim vegetation within the previously disturbed area. This is generally acceptable provided damage is repaired and reclaimed following use.

To reduce final reclamation costs; maintain healthy, biologically active topsoil; and to minimize habitat, visual, and forage loss during the life of the well, all salvaged topsoil should be spread over the area of interim reclamation, rather than stockpiled.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). Interim reclamation is to be completed within 6 months of well completion.
- 3. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with interim reclamation as per approved APD or Sundry Notice. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 4. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 5. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist

Solomon Hughes Natural Resource Specialist 575-234-5951

Douglas Hoag Civil Engineering Technician 575-234-5979