Form 3160-5

OCD-HORDS APPROVED

(March 2012)	UNITED STATES EPARTMENT OF THE INTE	RIOR HOBBS	OM B No	o. 1004-0137 October 31, 2014	
BU	REAU OF LAND MANAGE	MENT JUL 19	2016 5. Lease Serial No.		
Do not use th	Y NOTICES AND REPORTS (Is form for proposals to drill Ill Use Form 3160-3 (APD) fo	or to re-enteranECE	VED 6. If Indian, Allottee or	M125057	
SUBMIT IN TRI	PLICATE - Other instruction	7. If Unit of CA / Agreer	7. If Unit of CA / Agreement, Name and/or No.		
✓ Oil Well	Gas Well Other		8. Well Name and No. East Drinka	ard Blinebry Unit #16	
2. Name of Operator Apache Corporation			9. API Well No.	9. API Well No. 30-025-06526	
3a. Address 3b. Phone No. (include area code) 303 Veterans Airpark Ln, Midland, Tx 79705 432-556-9143				10. Field and Pool, or Exploratory Area Eunice; B-T-D, North (22900)	
Location of (Footage, Sec., T., R., or Survey Description) 330' FNL & 480" FEL, UL A, Sec 11, T21S, R37E				11. County or Parish, State Lea, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF NO	TICE, REPORT, OR OTHER D	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resume) Reclamation	INT TO PA PM	
Subsequent Report	Casing Repair	New Construction	Recomplete	P&A NR P&A R	
Final Abandonment Notice	Change Plans Convert to Injection	✓ Plug and Abandon ☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal	arily Abandon	
f the proposal is to deepen direction	ally or recomplete horizontally, give	ve subsurface locations and m	ed starting date of any proposed work	ll pertinent markers and zones.	

Attach the Bond under which the work will be performed or provide the bond No. on file with the BLM / BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

WITNESS

Apache Corporation proposes to P&A the above mentioned well by the attached procedure. A closed loop system will be used for all fluids from this wellbore and disposed of required by OCD Rule 19.15.17.

SUBJECT TO LIKE APPROVAL BY STATE

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Title Sr. Reclamation Foreman		
Date	7APPROVED	
DERAL OR STA	TE OFFICE USE	
Title	Date	
Office	Paul M Swanh BUREAU OF LAND MANAGEMENT	
	Date DERAL OR STA Title	

MWOCD 7/19/2016



8041


w/ 940 sx, TOC @ 2650' by TS

 LEASE NAME
 EBDU


 WELL #
 16

 API #
 30-025-06526

 COUNTY
 Lea, NM



PBTD @ 6510' TD @ 8041'



Conditions of Approval, Template

Apache Corporation East Drinkard Blinebry Unit - 16, API 3002506526 T21S-R37E, Sec 11, 330FNL & 480FEL July 12, 2016

- 1. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location during this workover operation.
- 2. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Notify 575-393-3612 Lea Co as work begins. Plugging procedures are to be witnessed. If there is no response leave a voice mail with the API#, workover purpose, and a call back phone number.
- 5. Surface disturbance beyond the existing pad must have prior approval.
- A closed loop system is required. The operator shall properly dispose of drilling/circulating
 contents at an authorized disposal site. Tanks are required for all operations, no excavated
 pits.
- 7. Functional H₂S monitoring equipment shall be on location.
- 8. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during any other crew-intensive operations.
- 10. The BLM PET witness is to run tbg tally and agree to cement volumes and placement. Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.
- 11. Cementing procedure is subject to the next three numbered paragraphs.
- 12. Mix cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft to the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ½" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- 13. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.

- 14. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 15. Remove the CIBP set at 5694 09/24/2014.
- 16. Remove the RBP set at 6188 03/07/1986.
- 17. Remove the unreported CIBP shown on Apache's diagram at 6510.
- 18. Tag the PBTD above the CIBP set at 7800 04/1964 and set a cement plug from that depth. Tag the plug with tubing and confirm a 200ft or greater plug has been set.
- 19. Set a CIBP within 100ft of the perfs at 6912-7379 and place a cement plug from that depth. Tag the plug with tubing and confirm a 200ft or greater plug has been set.
- 20. Set a CIBP within 100ft of the perfs at 5741-6115 and place a cement plug from that depth. Tag the plug with tubing and confirm the plug covers up to 5150.
- 21. PUH & spot a Class "C" cmt from 4107-3759. WOC & tag w/tubing at 3759 or above.
- 22. Submit evidence of 7" casing cement bond from 3202 to above 3102 or perf at 3202 and squeeze cement across the 9 5/8" shoe to above 3102. Tag the plug with tubing at 3102 or above.
- 23. Complete Steps 4, 5, & 6 of the proposed procedure as written.
- 24. File **subsequent sundry** Form 3160-**5** within 30 days of workover procedures. Submit the (BLM Form 3160-**5** subsequent report (daily reports) via BLM's Well Information System; https://www.blm.gov/wispermits/wis/SP (email pswartz@blm.gov for operator setup instructions). Include (dated daily) descriptions of the well work, ie. procedure descriptions and setting depths of each plug in the subsequent sundry.
- 25. Wellbore plugging is to be accomplished within 90 days of approval.

Reclamation Objectives and Procedures

In Reply Refer To: 1310

Reclamation Objective: At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as needed. This will apply to well pads, facilities, and access roads. Barricade all access road(s) at the starting point. If reserve pits have not been adequately reclaimed due to salts or other contaminants, propose a plan for BLM approval to provide restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations should have included adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For locations and/or access roads not having an approved plan, or an inadequate plan for surface reclamation the operator must submit a proposal describing the procedures for reclamation. The appropriate time for submittal would be when filing the Notice of Intent, or with the Subsequent Sundry Report of Abandonment on Form 3160-5. The final reclamation goal is to be completed within 6 months of wellbore abandonment.
- 3. With an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It may be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives.
- Upon reclamation conclusion submit a Form 3160-5, Subsequent Report of Reclamation.
 This will prompt a BLM specialist to inspect the location to verify work was completed
 as per approved plans.
- 5. The BLM approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been tentatively reestablished. If the objectives have not been met BLM will be notify the operator of the required corrective actions.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time the full BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the full BLM objectives have been met, submit a Final Abandonment Notice (FAN) Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time a BLM specialist will again inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability for the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell) Robertson, Jeffery Natural Resource Specialist 575-361-2632

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Jesse Bassett Natural Resource Specialist 575-234-6237

Paul Murphy Natural Resource Specialist 757-499-6869 Brooke Wilson Natural Resource Specialist 575-234-5913

Richard (Chad) Young Natural Resource Specialist 575-361-3565