
Submit I Copy To Appropriate District Office	State of New Mexico			Form C-103 Revised July 18, 2013	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	. Hobbs, NM 88240 148-1283 OIL CONSERVATION DIVISION 1334-6178 d., Aztec, NM 87410 476-3460 OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-30949	Revised July 16, 2013	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM			5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUSBBS PROPOSALS.)			7. Lease Name or Unit Agreement Name East Corbin Delaware Unit ✓		
1. Type of Well: Oil Well	ell Gas Well X Other 07/19/2016		8. Well Number 3	V	
Name of Operator EOG Resources, Ir	THE STEET		9. OGRID Number 7377		
3. Address of Operator P.O. Box 2267 Midland, TX 79702			10. Pool name or Wildcat Corbin; Delaware, West		
4. Well Location	660 South	1 190	80 1890	East ✓	
Unit Letter	:feet from the	Range 33E	feet from the	line	
Section	Township 18S 11. Elevation (Show whether L 3865' GR			ounty Lea	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or co of starting any proposed proposed completion or EOG Resources propos 1. MIRU pulling unit. P 2. MIRU wireline unit. I 3. Set 5-1/2" CIBP at 5 4. Dump bail 35' (±4sx CIBP. 5. Circulate 9.0 ppg mi 6. Spot 25sx Class C (6)	CHANGE PLANS MULTIPLE COMPL MULTIPLE COMPL MULTIPLE COMPL MULTIPLE COMPL CHANGE PLANS CHANGE P	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Ill pertinent details, and AC. For Multiple Con d NU the 2M BOP. 90' to 5,245'). RDMO w minimum of 4 hours. R	I give pertinent dates, in appletions: Attach wellbeine. If with work string and it.	ore diagram of	
9. Perforate 5-1/2" cas	g 1,500' verify cmt to 3 ing @ 730' and squeeze 160sx Class	s C, or until cement rea	aches surface. Ensure c	ement is at surface in all	
annuluses. 10. Weld on P&A marke	er. Cut off anchors 3' below surface.	Clean location. — L	PC Area. Inst		
Spud Date:		OCD 24 HOURS F ING OPERATIONS	PRIOR TO BEGINNII	ng grade. Take photo	
I hereby certify that the informati	on above is true and complete to the	best of my knowledge	and belief.		
SIGNATURE Star W.	TITLE RE	egulatory Analyst	DATE	7/19/2016	
Type or print name Stan Wag			PHONE	3: 432-686-3689	
For State Use Only APPROVED BY:	Whitalam TITLE Petr	oleum Engr.	pecialist DATE	7/19/2016	
Conditions of Approval (if any):	Must Be Notified				
	beginning of Plug	ging Operation	ons.		



East Corbin Delaware Unit #3 WIW

660' FSL, 1980' FEL Section 16, T18S, R33E Lea County, New Mexico API No. 30-025-30949

OCD - HOBBS 07/19/2016 RECEIVED





East Corbin Delaware Unit #3 WIW

660' FSL, 1980' FEL Section 16, T18S, R33E Lea County, New Mexico API No. 30-025-30949

OCD - HOBBS 07/19/2016 RECEIVED

