



3002506442

Internal Incident Report – Spill/Release

HOBBS OCD

AUG 09 2012

RECEIVED

Location: WBDU #5

Production Area: Eunice North

District: New Mexico

Date: 08/01/12

Time: 7am

One Line Summary: Internal corrosion deteriorated the 2" line in the middle of the Victaulic clamp groove.

Full summary: Pumper arrived at the location and found that the injection well was leaking. At that time the pumper turned the well off. The mechanic disconnected the corroded pipe and replaced with a new section of pipe. This corroded pipe was plastic coated with tongue and groove. A vacuum truck was dispatched to the location to remove all standing fluid. Approximately 125bbls of produced water was released and approximately 120bbls of produced water was recovered. The release affected the location, lease road and the pasture area. The total affected area was 19,933 square feet. A backhoe was dispatched immediately to build a temporary road around the affected area for proper traffic flow. An emergency one-call has been placed and the initial assessment is being conducted at this time.

Root cause of incident:

Corrective Actions:

- **Once the pipe is properly tongued and grooved, it will be sent in for coating before replacement takes place.**

Reported by: Natalie Gladden (575-390-4186)



Internal Corrosion on inside of plastic coated pipe.

