Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
		ral Resources	Revised August 1, 2011 WELL API NO.	
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 882 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 FED 2 0 1220 South St. Francis Dr			30-025-36934	
District III – (505) 334-6178 FFR 26 20-1220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 FEB 26 2018 Santa Fe, NM 87505 District IV - (505) 476-3460			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NMRECEIVED			19552	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			North Hobbs (G/SA) Unit	
PROPOSALS.)			8. Well Number B Hardin 001	
1. Type of Well: Oil Well Gas Well Other: 2. Name of Operator			9. OGRID Number: 192463	
OXY USA WTP			9. OGKID Nulliber. 192403	
3. Address of Operator			10. Pool name or Wildcat:	
P.O. Box 4294, Houston, Tx 77210			Glorieta	
4. Well Location (Surface) Unit Letter D: 410	fact from the North line	and 249 fa	at from the West line	
Unit Letter D _:410feet from the _North line and348feet from theWest line Section 19				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				County
368	86' (KB)			
12 61 1 1		227	0.1. 0.	
12. Check Appr	opriate Box to Indicate Na	ature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPO				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORL				
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT				
DOWNHOLE COMMINGLE	DETIL EE COMIT E	OAGING/OLIVIEN	30B	
OTUED:		OTHER.		
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recomple	etion.			
1) MIRU PU. ND Wellhead. NU B	OP.			
2) POOH w/ Beam Equipment				
 3) Drill out CIBP at 6620' down to ±7550' 4) RIH with new CIBP and set at 7066' (50' from top perf) During 			this procedure we plan to use	
5) Cap CIBP with 25 sx cement the clo			sed-loop system with a steel	
6) Circulate mud laden fluid to surface			nd haul contents to the required	
7) Spot 25 sx cement from 6650'-6410' (Drinkard/Tubb plug) 8) Spot 40 sx cement from 5750'-5350' (Blinebry/Glorieta plug) disposal per ODC				
9) Tag and confirm TOC				
10) Perform MIT to confirm top plug	g is holding pressure			
11) POOH with tubing 12) ND BOP, NU Wellheads ar or a	4		* *	****
12) ND BOP. NU Weddie and 15.25 (13) RDMO PU. Put well only produced to the pr	etion	Condi	tion of Approval: notify	
Set CIBP, RBP or Packer within 1	OU feet of uppermost			1
Kid Keleace liate.			Hobbs office 24 hours	
a pressure drop of not greater		prior of a	unning MIT Test & Cha	rt 📜
30 minute period				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE TITLE Production Engineer DATE 02/26/2018				
Type or print name Jacob S. Cox E-mail address: Jacob Cox@oxy.com PHONE: 713-497-2053				
For State Use Only				
APPROVED BY:	Drownitle	ADII	DATE 2/2	26/2018
Conditions of Approval (if any):		, , - , -	DAIL	

NO PROD REPORTED - 16 MONTHS

MB



