

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator MGF Oil Corporation	8. Farm or Lease Name Berry, et al
3. Address of Operator 700 Vaughn Bldg., Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>11-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Field Ranch, Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) GR 3874	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug @9400'. Dump 35' cement on top of bridge plug.
 Cut 5 1/2@approx. 8400'. Pull all 5 1/2.
 Run tbg. to 8450'. Circulate mud through tbg.
 Spot 30 Sk. plug in and above cut 5 1/2.
 Spot 30 Sk. plug from approx. 5900-6000. Pull tbg.
 Cut 8 5/8 @2000. Pull 8 5/8. Run tbg. 120' Pull 1/2" string 2050 1950
 Spot 60 Sk. plug from approx. 1860-1960.
 Spot 60 Sk. plug in and below 11 3/4 shoe from approx. 335-435.
 Set 10 Sk. plug @surface.
 Install marker.

Estimated date of starting - 2-15-76

THE OPERATOR MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PRODUCE OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jesse L. Roberts TITLE Engineer DATE 2-10-76

APPROVED BY Jerry Simon TITLE Dist. Eng. DATE 2-10-76

CONDITIONS OF APPROVAL, IF ANY: