

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
-	
7. Unit Agreement Name	
D. Q. S. U.	
8. Farm or Lease Name	
Tract 29	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
Caprock Queen	
12. County	
Chaves	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Water Injection</b>
2. Name of Operator <b>Cities Service Oil Company</b>
3. Address of Operator <b>Box 69 - Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>J</b> , <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>2</b> TOWNSHIP <b>14S</b> RANGE <b>31E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) -

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- We propose to plug and abandon the above well in the following manner:**
- 1. Set CI bridge plug in casing just above open hole. (5 1/2" set @ 3080 w/100 sxs)**
  - 2. Set 25 sack cement plug on top of bridge plug.**
  - 3. Load hole with mud laden fluid.**
  - 4. Set 10 sack cement surface plug with a 4" dry hole marker.**
  - 5. Clean location of all debris and equipment.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED  
C. D. ROBERTSON

SIGNED \_\_\_\_\_ TITLE **District Admin. Supervisor** DATE **5/4/70**

APPROVED BY  TITLE **SUPERVISOR DISTRICT** DATE **MAY 7 1970**

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION COMM.  
HCBBS, N. H.

MAY 6 1970

RECEIVED