

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Charles B. Gillespie, Jr.

3. Address of Operator

P. O. Box 8 Midland, Texas 79702

4. Well Location

Unit Letter P : 660 Feet From The South Line and 660 Feet From The East Line

Section 33

Township

14S

Range

33E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4197' DF

7. Lease Name or Unit Agreement Name

Stevens

8. Well No.

1

9. Pool name or Wildcat

Saunders Permo Upper Penn

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Cut off and pull 5 1/2" casing from approximately 4900'.
2. Set 25 sx plug across 5 1/2" casing stub.
3. Set 25 sx plug across 8 5/8" casing shoe at 4164'.
4. Cut off and pull 8 5/8" casing from approximately 600'.
Top of cement outside 8 5/8" casing at 660' (temperature survey).
5. Set 50 sx plug across 8 5/8" casing stub.
6. Set 25 sx plug across 13 3/8" casing shoe at 296'.
7. Set 10 sx plug at top of surface casing.
8. Weld 4" marker to surface pipe, and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

David W. Hastings

TITLE

Production Manager

DATE

12/28/90

TYPE OR PRINT NAME

David W. Hastings

TELEPHONE NO. 915-683-1765

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 6 2 1991

77-1110

DEC 31 1990

COE
HOUSE LORRAE