STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

MB. BY COPIES SCCEIVED	1	
DISTRIBUTION	!	
SANTA FE		
FILE		
U.S.O.S.		
LAND OF FICE		
OPERATOS		ĺ

DISTAIRUTIO SANTA FE FILE) N		P. O. BOX 20	ากล			Form C-103
<u> </u>				, , ,			Revised 10-1-
FILE		SAN	ITA FE, NEW ME	EXICO 87501			REVINED 15-1-
					[5]	a, Indicate Typ	e of Lerise
U.S.O.S.						·	Fee
LAND OFFICE					 	, State Oil & G	
OPERATOR					1	E-7555	45 1,40.4 140.
						E-1333	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
	SUNDRY	Y NOTICES AND	REPORTS ON WE	LLS			
HT 360 TO4 OO)	15 FORM FOR PROF USE "APPLICATION	FOSALS TO DRIVE OR T ON FOR PERMIT —"" (F	O DEEPEN OR PLUG BACK! CRM C-1011 FCR BUCH PR	TO A DIFFERENT RESIRVOL OPOSALS.)	••		
1.				,	7	, Unit Agreeme	nt Nome
on X	WELL .	CTHER-					
2. Name of Operator		0171.			e	. Form or Leus	e Nume
Rapid Company,	Inc.				1	McKay Stat	
3. Address of Operator		endon Ten	Dam 760 11:1	L - 10/ 000/0	9	, Well No.	
c/o off kebort	es a Gas Se	ervices, inc.	, Box 763, Hob	DB, NM 88240		2	
4. Location of Well					1	0. Fileld and Fo	ool, er Wildcar
	0	660	South	1980		Caprock Qu	ieen
UNIT LETTER		FEET FROM	4 THEL	INE AND	FEET FROM	immin	MALLINI
East		18	139	32F			
THE	LINE, SECTIO	NT	OWNSHIP	RANGE	имем. 🖯	illilli)	
						777777	7.4.4.4.4.4.4.
THITHIN .		///// 15. Eleva	tion (Show whether DF,		ì <u> </u>	2. County	
	//////////		4362.	6 GL	[]	Lea	
; e. ; e.		ppeoperate De-	To Indiana Mari	to of Nation Page	et of Other	Data	
		• • •	To moreate watu	re of Notice, Repo			
NO	OTICE OF IN	TENTION TO:		SUBS	EQUENT F	REPORT OF	:
					<u></u>		r
PERFORM REMEDIAL WOR	к [PLUG	AND ABANDON X RE	MEDIAL WORK		ALTE	RING CASING
TEMPORARILY ABANDON			co	MMENCE DRILLING OPHS.		PLUG	AND ABANDONMENT
	Ħ	CHAN	IGE PLANS CA	SING TEST AND CEMENT JQ	. [No com
PULL OR ALTER CABING	لـــا	CHAN	1	Sunn I am		ll History	7 🛛
				OTHER DUPPTEM			
OTHER			1 11				
17. Describe Proposed of twork) SEE RULE 1	103.			and give pertinent dates			starting any propose
	Perforat gallons and sand line at It is probe made by-pass cement.	ed 2 7/8" tu 15% acid in 1 line in hol 850'. coposed to pl to pump flui sand line an If fluid wi	bing 2996 to 3 two stages. Se. Unable to ug and abandon d past sand lid swab, hole will not by-pass	ond give pertinent dates 050 and treated tarted swabbing fish sand line. as follows: A ne and swab. I ill be filled t sand line and surface with ce	with 170 Lost a Top of n attempa f fluid a o surface swab, ho	00 swab sand t will will e with	starting any propos
WORK) SEE RULE 1	Perforat gallons and sand line at It is probe made by-pass cement. above sa	ed 2 7/8" tu 15% acid in 1 line in hol 850'. coposed to pl to pump flui sand line an If fluid wi and line will	two stages. See. Unable to ug and abandon d past sand 11 d swab, hole w 11 not by-pass be filled to	050 and treated tarted swabbing fish sand line. as follows: A ne and swab. I ill be filled t sand line and surface with ce	with 170. Lost a Top of n attempt f fluid woo surfaceswab, holdert.	00 swab sand t will will e with le	
1910rk) SEE RULE 1	Perforat gallons and sand line at It is probe made by-pass cement. above sa	ed 2 7/8" tu 15% acid in 1 line in hol 850'. coposed to pl to pump flui sand line an If fluid wi and line will	two stages. See. Unable to ug and abandon d past sand 11 d swab, hole w 11 not by-pass be filled to	050 and treated tarted swabbing fish sand line. as follows: A ne and swab. I ill be filled t sand line and surface with ce	with 170. Lost a Top of n attempt f fluid woo surfaceswab, holdert.	00 swab sand t will will e with le	starting an, proposi
1910rk) SEE RULE 1	Perforat gallons and sand line at It is probe made by-pass cement. above sa	ed 2 7/8" tu 15% acid in 1 line in hol 850'. coposed to pl to pump flui sand line an If fluid wi and line will	two stages. See. Unable to ug and abandon d past sand 11 d swab, hole w 11 not by-pass be filled to	050 and treated tarted swabbing fish sand line. as follows: A ne and swab. I ill be filled t sand line and surface with ce	with 170. Lost a Top of n attempt f fluid woo surfaceswab, holdert.	00 swab sand t will will e with le	
1910rk) SEE RULE 1	Perforat gallons and sand line at It is probe made by-pass cement. above sa	ed 2 7/8" tu 15% acid in 1 line in hol 850'. coposed to pl to pump flui sand line an If fluid wi and line will	two stages. See. Unable to ug and abandon d past sand 11 d swab, hole w 11 not by-pass be filled to	050 and treated tarted swabbing fish sand line. as follows: A ne and swab. I ill be filled t sand line and surface with ce	with 170. Lost a Top of n attempt f fluid woo surfaceswab, holdert.	00 swab sand t will will e with le	
1910rk) SEE RULE 1	Perforat gallons and sand line at It is probe made by-pass cement. above sa	ed 2 7/8" tu 15% acid in 1 line in hol 850'. coposed to pl to pump flui sand line an If fluid wi and line will	two stages. See. Unable to ug and abandon d past sand 11 d swab, hole w 11 not by-pass be filled to	050 and treated tarted swabbing fish sand line. as follows: A ne and swab. I ill be filled t sand line and surface with ce	with 170. Lost a Top of n attempt f fluid woo surfaceswab, holdert.	00 swab sand t will will e with le	