

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-2118

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Charles B. Gillespie, Jr.

3. Address of Operator

P. O. Box 8 Midland, Texas 79702

7. Lease Name or Unit Agreement Name

State 'G'

8. Well No.

7

9. Pool name or Wildcat

Saunders Permo Upper Penn

4. Well Location

Unit Letter D : 800 Feet From The North Line and 660 Feet From The West Line

Section 3 Township 15-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4206' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cast iron bridge plug above perforations at 9750'.  
Dump 4 sx cement on top of bridge plug, WOC.
2. Set 25 sx plug at 7700' across top of ABO.
3. Cut off and pull 5 1/2" casing from approximately 6500'.
4. Set 25 sx plug across 5 1/2" casing stub.
5. Set 25 sx plug across 8 5/8" casing shoe at 4200'.
6. Cut off and pull 8 5/8" casing from approximately 1200'.
7. Set 50 sx plug across 8 5/8" casing stub.
8. Set 25 sx plug across 13 3/8" casing shoe at 296'.
9. Set 10 sx plug at top of surface casing.
10. Weld 4" marker to surface casing, and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David W. Hastings TITLE Production Manager DATE 7/18/89

TYPE OR PRINT NAME David W. Hastings TELEPHONE NO. 915-683-1765

(This space for State Use)

**ORIGINAL SIGNED BY JERRY SEXTON**  
**DISTRICT I SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**JUL-20 1989**

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PRODUCTION FOR THE OIL  
OIL PRODUCTION

JUL 19 1989  
OCD  
HORRIS OFFICE