Office		State of New		Form C-1(
<u>District (</u> 1625 N. Fren	ch Dr., Hobbs, NM 87240	Energy, Minerals and	Natural Resources	Revised March 25, 19 WELL API NO.
District II	St. Artesia, NM 87210	OIL CONSERVAT	TON DISTISSION	30-025-21216
District III		2010 Canala		5. Indicate Type of Lease
1000 Rio Bra: <u>District (V</u>	zos Rd., Aztec, NM 8741	Santa Fe, Ni	-	STATE X FEE
2040 South Pa	icheco, Santa Fe, NM 875	05 Santa Pe, 141	M 9/303	6. State Oil & Gas Lease No.
(DO NOT USI DIFFERENT I PROPOSALS 1. Type of '	E T HIS FORM FOR PRO RESERVOIR USE "APF)	OTICES AND REPORTS ON WE POSALS TO DRILL OR TO DEEPEN OF PLICATION FOR PERMIT (FORM C-10	DI LIC PACY TO A	7. Lease Name or Unit Agreement Name:
Oil Weil	Gas Weil	Other Water Inje	ection Well	Mesa Queen Unit
2. Name o	-			8. Weil No.
3. Address	1 & Gas Corpor of Operator	ation		#24
PO Box 3	•	L. Texas 79702		9. Pool name or Wildcar
4. Weil Lo		<u>rexas 79702</u>		Mesa Queen Associated
	Letter E	1650 feet from the Nor		660 feet from the West line
Secti	on 20	Township 16S	Range 32E	NMPM County Lea
		10. Elevation (Show whether I	DR, RKB. RT. GR. e ic .,)
	II. Check A	4353' GR Appropriate Box to Indicate N	James of Marian D	
	NOTICE OF IN	TENTION TO:	valure of Nonce, R	leport or Other Data
PERFORM RE	MEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	EQUENT REPORT OF: ALTERING CASING
			THE POINT	ALIERING CASING L
			i	
TEMPORARIL	Y ABANDON	CHANGE PLANS	COMMENCE DRILL	
	_	CHANGE PLANS MULTIPLE COMPLETION	COMMENCE DRILL CASING TEST AND CEMENT JOB	ABANDONMENT
TEMPORARIL	_	MULTIPLE	CASING TEST AND CEMENT JOB	ABANDONMENT
TEMPORARIL' PULL OR ALTE	ER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB	ABANDONMENT
PULL OR ALTE OTHER: 12. Describe p	roposed or complete uny proposed work).	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER:	ABANDONMENT
OTHER: 12. Describe p of starting a or recompil	roposed or complete my proposed work).	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER:	ABANDONMENT
OTHER: 12. Describe p of starting a or recompil. 1. MIRU	roposed or complete try proposed work).	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple C	CASING TEST AND CEMENT JOB OTHER:	ABANDONMENT
OTHER: 12. Describe pof starting a or recompil. 1. MIRU 2. POOH	roposed or complete my proposed work). ation. PU w/2 3/8" tubin	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple C	CASING TEST AND CEMENT JOB OTHER:	ABANDONMENT
OTHER: 12. Describe pof starting a or recompil. 1. MIRU 2. POOH 3. RIH a	roposed or complete my proposed work). ation. PU w/2 3/8" tubin and retrieve BP	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple C	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach w	ABANDONMENT
OTHER: 12. Describe prof starting a or recompile 1. MIRU 2. POOH 3. RIH at 4. RIH w	roposed or complete uny proposed work). ation. PU w/2 3/8" tubin nd retrieve BP/packer and 2	MULTIPLE COMPLETION di operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SEE RULE 1	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach w	ABANDONMENT
OTHER: 12. Describe prof starting a or recompil. 1. MIRU 2. POOH 3. RIH at 4. RIH w 5. Load	roposed or complete my proposed work). ation. PU w/2 3/8" tubin nd retrieve BP/packer and 2 backside w/pac	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SE	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 '	ABANDONMENT pertinent dates, including estimated date veilbore diagram of proposed completion
OTHER: 12. Describe p of starting a or recompil. 1. MIRU 2. POOH 3. RIH a 4. RIH w 5. Load 6. Conta	roposed or complete my proposed work). ation. PU w/2 3/8" tubin and retrieve BP/packer and 2 backside w/pacct NMOCD to wi	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple Complete 1103. For Multiple	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 '	ABANDONMENT pertinent dates, including estimated date veilbore diagram of proposed completion
OTHER: 12. Describe p of starting a or recompil. 1. MIRU 2. POOH 3. RIH a 4. RIH w 5. Load 6. Conta 7. Press	roposed or complete my proposed work). PU w/2 3/8" tubin nd retrieve BP/packer and 2 backside w/pacct NMOCD to will ure test per N	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple Complete 1103. For Multiple	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 '	ABANDONMENT pertinent dates, including estimated date veilbore diagram of proposed completion
OTHER: 12. Describe p of starting a or recompil 1. MIRU 2. POOH 3. RIH a 4. RIH w 5. Load 6. Conta 7. Press 8. Nippl	roposed or complete my proposed work). ation. PU w/2 3/8" tubin and retrieve BP/packer and 2 backside w/pacct NMOCD to wi	MULTIPLE COMPLETION di operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. F	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 '	ABANDONMENT pertinent dates, including estimated date veilbore diagram of proposed completion
OTHER: 12. Describe p of starting a or recompil 1. MIRU 2. POOH 3. RIH a 4. RIH w 5. Load 6. Conta 7. Press 8. Nippl	roposed or complete by proposed work). PU w/2 3/8" tubin attorn. PU packer and 2 backside w/pacct NMOCD to will ure test per New packer and per New	MULTIPLE COMPLETION di operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. F	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 '	ABANDONMENT pertinent dates, including estimated date veilbore diagram of proposed completion
OTHER: 12. Describe p of starting a or recompil 1. MIRU 2. POOH 3. RIH a 4. RIH w 5. Load 6. Conta 7. Press 8. Nippl	roposed or complete by proposed work). PU w/2 3/8" tubin attorn. PU packer and 2 backside w/pacct NMOCD to will ure test per New packer and per New	MULTIPLE COMPLETION di operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. F	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 '	ABANDONMENT pertinent dates, including estimated date veilbore diagram of proposed completion
OTHER: 12. Describe p of starting a or recompil 1. MIRU 2. POOH 3. RIH a 4. RIH w 5. Load 6. Conta 7. Press 8. Nippl	roposed or complete by proposed work). PU w/2 3/8" tubin attorn. PU packer and 2 backside w/pacct NMOCD to will ure test per New packer and per New	MULTIPLE COMPLETION di operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. F	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 '	ABANDONMENT pertinent dates, including estimated date veilbore diagram of proposed completion
OTHER: 12. Describe prof starting a or recompil. 1. MIRU 2. POOH 3. RIH at 4. RIH with the starting at 4. RIH with the starting at 5. Load 6. Contate 7. Press 8. Nipple 9. Returning at 1.	roposed or complete my proposed work). Atton. PU w/2 3/8" tubin nd retrieve BP /packer and 2 backside w/pac ct NMOCD to wi ure test per N e up well, RDM n to water inj	MULTIPLE COMPLETION di operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. F	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we will be a series of the completions of the c	ABANDONMENT e perment dates, including estimated date veilbore diagram of proposed completion e motice)
OTHER: 12. Describe prof starting a or recompil. 1. MIRU 2. POOH 3. RIH at 4. RIH with the starting at 4. RIH with the starting at 5. Load 6. Contate 7. Press 8. Nipple 9. Returning at 1.	roposed or complete my proposed work). Atton. PU w/2 3/8" tubin nd retrieve BP /packer and 2 backside w/pac ct NMOCD to wi ure test per N e up well, RDM n to water inj	MULTIPLE COMPLETION di operations. (Clearly state all per SEE RULE 1103. For Multiple Complete SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. For Multiple SEE RULE 1103. F	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we will be a series of the completions of the c	ABANDONMENT e perment dates, including estimated date veilbore diagram of proposed completion e motice)
OTHER: 12. Describe prof starting a or recompil. 1. MIRU 2. POOH 3. RIH at 4. RIH with the starting at 4. RIH with the starting at 5. Load 6. Contate 7. Press 8. Nipple 9. Returning at 1.	roposed or complete my proposed work). Atton. PU w/2 3/8" tubin nd retrieve BP /packer and 2 backside w/pac ct NMOCD to wi ure test per N e up well, RDM n to water inj	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple Complete 1103. For Multiple	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 ** Eve 24 hr advances of my knowledge and completions.	ABANDONMENT e pertinent dates, including estimated date wellbore diagram of proposed completion e notice)
OTHER: 12. Describe profisarung a or recompil. 1. MIRU 2. POOH 3. RIH at 4. RIH w 5. Load 6. Conta 7. Press 8. Nippl 9. Return	roposed or complete my proposed work). ation. PU w/2 3/8" tubin nd retrieve BP/packer and 2 backside w/pacct NMOCD to will ure test per Ne up well, RDM n to water inj	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple Complete 1103. For Multiple	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 ** Eve 24 hr advances of my knowledge and completions.	ABANDONMENT e pertinent dates, including estimated date veilbore diagram of proposed completion e notice) d belief. Analyst DATE 6/13/01 915-683-3650
OTHER: 12. Describe profisarting a or recompile 1. MIRU 2. POOH 3. RIH at 4. RIH w 5. Load 6. Conta 7. Press 8. Nippl 9. Return I hereby cerroy that SIGNATURE Type or print name	roposed or complete my proposed work). ation. PU w/2 3/8" tubin and retrieve BP/packer and 2 backside w/pacct NMOCD to will ure test per Ne up well, RDM and to water inj	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple Complete 1103. For Multiple	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 ** Eve 24 hr advances of my knowledge and completions.	ABANDONMENT e pertinent dates, including estimated date veilbore diagram of proposed completion e notice) d betier. Analyst DATE 6/13/01
OTHER: 12. Describe pof starting a or recompil. 1. MIRU 2. POOH 3. RIH at 4. RIH wt 5. Load 6. Contat 7. Press 8. Nippl 9. Return I hereby cereby that SIGNATURE	roposed or complete my proposed work). ation. PU w/2 3/8" tubin nd retrieve BP/packer and 2 backside w/pacct NMOCD to will ure test per Ne up well, RDM n to water inj	MULTIPLE COMPLETION d operations. (Clearly state all per SEE RULE 1103. For Multiple Complete 1103. For Multiple	CASING TEST AND CEMENT JOB OTHER: runent details, and give Completions: Attach we ker @ 3375 ** Eve 24 hr advances of my knowledge and completions.	ABANDONMENT e pertinent dates, including estimated date veilbore diagram of proposed completion e notice) d belief. Analyst DATE 6/13/01 915-683-3650