

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instruction
verse side)Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0315712

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection Well	7. UNIT AGREEMENT NAME Maljamar (Grayburg)
2. NAME OF OPERATOR Chevron Oil Company	8. FARM OR LEASE NAME Maljamar Unit
3. ADDRESS OF OPERATOR P. O. Box 1660, Midland, Texas	9. WELL NO. 44
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit 1, 1980' FSL, 660' FWL, Section 9, T-17-S, R-32-E, NMPM	10. FIELD AND POOL, OR WILDCAT Maljamar (Grayburg-San Andres)
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 4065
12. COUNTY OR PARISH Lea	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work to commence third quarter 1975. Federal office will be notified prior to commencing actual plugging operations.

1. Dig pit and cellar.
2. Run in hole with tubing, open ended, to 3700', displace hole with 9.5 ppg mud laden fluid. Spot 25 sxs cement. Pull tubing to 2400' and spot 30 sxs cement. Pull tubing to 1000' and spot 35 sxs cement. Pull out of hole with tubing.
700' 2500'
3. Perforate 4 1/2" casing at 348'. Establish circulation, pump sufficient cement to circulate to surface via annulus leaving 4 1/2" casing full.
4. Cut off casing 2-3' below ground level, set 4' marker. Back fill pits and cellar. Clean up location as per federal or state requirements.

18. I hereby certify that the foregoing is true and correct

SIGNED

E. T. Kryshuk

TITLE Division Drilling Supt.

DATE July 30, 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

AUG 19 1975

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side