

0125-01761

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**E 7525**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <b>D A &amp; S Oil Well Servicing, Incorporated</b>	8. Farm or Lease Name <b>State 32</b>
3. Address of Operator <b>P. O. Box 657, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>B</b> <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>410</b> FEET FROM THE <b>East</b> LINE, SECTION <b>32</b> TOWNSHIP <b>18S</b> RANGE <b>39E</b> NMPM.	10. Field and Pool, or Wildcat <b>Texline Penrose Gas</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3600 GL</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Ran and set 2-7/8" CIBP @ 3800' and capped w/2 sx. cmt. (Est. top @ 3730')
2. Cut 2-7/8" csg. @ 3508'. Broke circ. and circ. hole w/MLF.
3. Spotted 50 sx. cmt. plug on stub @ 3508'.
4. POH w/2-7/8" to 1800' and spotted 50 sx. cmt. plug in bottom of 8-5/8"
5. POH w/2-7/8" and spotted 10 sx. cmt. plug in top of 8-5/8".
6. Cut off well head and installed dry hole marker.

Work completed on 6-21-74

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Paul Blis* TITLE Vice President DATE 7-17-74

APPROVED BY *Nathan E. Clegg* TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: