DISTRICTION   Section   P.O. Box 2088   Santa Fe, New Mexico 87504-2088   Sidiciae Type of Lease   STATE   FE   Section   Se	to Appropriate District Office	<b></b> .			
### STATE   FE	P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			WELL API NO.	
SUNDRY NOTICES AND REPORTS ON WELLS				5. Indicate Type of Lease  STATE FEE X	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON FOR PERMIT  DIFFERENT RESERVOR. USE 'APPLICATION FOR PERMIT  1. Type of Well:  OBD.	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON FOR PERMIT  DIFFERENT RESERVOR. USE APPLICATION FOR PERMIT  1. Type of Well:  OBL. OTHER  SECTION 32  N. HOBBS (6/SA) UNIT  SECTION 32  SECTION 32  N. HOBBS (6/SA) UNIT  SECTION 32  SECTION 32  N. HOBBS (6/SA) UNIT  SECTION 32  SECTION 32  SECTION 32  N. HOBBS (6/SA) UNIT  SECTION 32  SECTION 32  SECTION 32  SECTION 32  N. HOBBS (6/SA) UNIT  SECTION 32  SE	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OH PLUG BACK TO A				
1. Type of Well:    State   St				N. HOBBS (G/SA) UNIT	
2. Name of Operator  SHELL WESTERN E & P INC. (4431 WCK)  3. Address of Operator  P. O. BOX 576. Houston. TX 77001-0576.  4. Well Location  Unit Letter C: 639 Feet From The North Line and 1885 Feet From The West Line  Section 32 Township 18-S Range 38-E NMFM LEA County  10. Elevation (Schow whether DF, KKB, KT, GR, etc.)  3636 ' GR  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including enimeted date of starting any proposed work) SEE RUILE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals  15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  I heardy certify that the information above is true and complete to the best of my knowledge and balld.  W.F.N. KELLDORF TITE. STAFF PRODUCTION ENGINEER DATE MAR 3 0 1989  SKINATURE COMMENCE DRILLING CASING TITE.	1. Type of Well: OIL CVI OLS COLORED				
SHELL WESTERN E & P INC. (44.51 W.K.)  Address of Operator  P. O. BOX 576. Houston, TX 77001-0576  4. Well Location  Unit Latter C: 639 Feet From The North lise and 1885 Feet From The West Liae  Section 32 Township 18-S Range 38-E NMFM LEA County  10. Elevation (Show whether DF, RKB, KT, GR, etc.)  3636' GR  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  TEMPORAHILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including entimated date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals  15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  Thomby certly that the information above is true and complete to the lest of my knowledge and belief.  W.F.N.: KELLDORF Time STAFF PRODUCTION ENGINEER MAR 3 0 1989	2. Name of Operator				•
P. O. 80X 576   Houston TX 77001-0576   HUBBS (G/SA)					
Well Lection  Unit Letter C: 639 Feet From The North Line and 1885 Feet From The West Line  Section 32 Township 18-S Range 38-E NMFM LEA County  10. Elevation (Show whether DF, RKE, KT, GR. etc.)  3636' GR  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DEFILLING OPNS. PLUG AND ABANDONMENT COMMENCE DEFILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent acts, including estimated date of starting any proposed work) SEE KULE 1103.  2-20-89 thru 2-21-89:  POOH W/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' W/ 1200 gals  15% HC1 acid + 44 ball sealers, using pkr set @ 4097'. RIH W/ prod equip.  Returned well to production 2-21-89.  1hereby certify that the information above is true and complete to the best of my knowledge and belief.  W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989	TU 77001 0576			HOBBS (G/SA)	
Section 32 Township 18-5 Range 38-E NMTM LEA County    10. Elevation (Show whether DF, RKB, RT, GR, etc.)   3636' GR   3636' GR   11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:    PERFORM REMEDIAL WORK	4. Well Location		. 100		11
Section 10. Elevation (Show whether DF, RRB, RT, GR, etc.)  3636' GR  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89: POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals 15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip. Returned well to production 2-21-89.	Unit Letter : 639	Feet From The North	Line and188	Feet From The	West Line
Section 10-Blevation (Show whether DF, RKB, RT, GR, etc.)    3636   GR	32		38-E	NMPM LEA	County
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM FEMEDIAL WORK	Section			V///	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all perincent details, and give perincent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals  15% HC1 acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPOPARTILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including enimated date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals 15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  Ibereby certify that the information above is true and complete to the best of my knowledge and belief.  STAFF PRODUCTION ENGINEER MAR 3 0 1989  STAFF PRODUCTION ENGINEER MAR 3 0 1989					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  PULL OR ALTER CASING OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including entirested date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres .4135 = 4256' w/ 1200 gals  15% HC1 acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.	NOTICE OF INT	ENTION TO:	SUE	BSEQUENT REPO	rition:
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:  OTHER:  AT  OTHER:  AT  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals  15% HC1 acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SKINATURE WE STAFF PRODUCTION ENGINEER MAR 3 0 1989  TELEPHONE NO.	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTER	RING CASING
CASING TEST AND CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals  15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SKNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989		CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG	AND ABANDONMENT
OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals 15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SKONATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989	CACING TEST AND CENENT FOR				
2-20-89 thru 2-21-89:  POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals  15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SHONATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989  TELEPHONE NO.	,		OTHER:	AT ·	[X
POOH w/ prod equip. C0 to 4305'. AT San Andres 4135 = 4256' w/ 1200 gals  15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIONATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989  TELEPHONE NO.	12. Describe Proposed or Completed Operawork) SEE RULE 1103.	tions (Clearly state all pertinent details, ar	nd give pertinent dates, incl	uding estimated date of startin	g any proposed
15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SKONATURE W.F.N.: KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989	2-20-89 thru 2-21-89:	·.			
15% HCl acid + 44 ball sealers, using pkr set @ 4097'. RIH w/ prod equip.  Returned well to production 2-21-89.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SKONATURE W.F.N.: KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989	POOH w/ prod equip. C	0 to 4305'. AT San And	dres .4135 = 42	256' w/ 1200 gals	5 .
Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  W.F.N.: KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989  TELEPHONE NO.					•
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SWINATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER MAR 3 0 1989					
SIGNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE MAR 3 U 1300	Returned werr to produ				
SIGNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE MAR 3 U 1300					
SIGNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE MAR 3 U 1300					
SIGNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE MAR 3 U 1300	•				
SIGNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE MAR 3 U 1300	•		•		
SIGNATURE W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE MAR 3 U 1300		and annual at a the hard of my broadlander on	d belief		
TELEPHONE NO.	I hereby certify that the information above is tr	WE WILL WELL DODE	STAFF PROF	DUCTION FNGINFER	MAR 3 0 1989
	SIONATURE DEN KALLEY	N.J. M. KELLDUKI T	TE SIMI INOL	DOCUMENTAL TO	A12
	TYPE OR PRINT NAME				есерноме но.

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APR 4 1989

\_\_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: