

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-23960
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name State J
Well No. 8
Pool name or Wildcat Vacuum Grbg/San Andres
Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1780</u> Feet From The <u>East</u> Line 22 Section <u>22</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>Lea</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL GAS WELL OTHER

Name of Operator
Exxon/Mobil Corporation

Address of Operator
PO Box 4358 Houston, Texas 77210-358

Well Location
Unit Letter G : 1980 Feet From The North Line and 1780 Feet From The East Line

22 Section 22 Township 17S Range 34E NMPM Lea County

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify NMOCD of Intent to plug and abandon
Top of fish 3994' Collapsed casing @ 3445' *Tag to Fish*

- 1.) TIH W/ Packer to 3900'. Establish injection rate. TOH
- 2.) Set CICR @ 3900' Squeeze 100 sacks of cement WOC & Pressure test. *capw/50' cmr*
- 3.) Circ. well with mud
- 4.) Spot 100' of cement @ 2250'-2100' (Salt)
- 5.) Spot 100' of cement @ 410'-310' (Shoe) WOC & Tag
- 6.) Spot 10 sack surface plug
- 7.) Cut off wellhead & anchors 3' BGL. Cap well with steel plate. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Jack Shelton* TITLE Agent DATE 11-27-00

TYPE OR PRINT NAME Jack Shelton TELEPHONE NO. 915-523-5155

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

PH

