

NEW MEXICO OIL CONSERVATION COMMISSION

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name J. R. Phillips
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 4
4. Location of Well UNIT LETTER <u>B</u> <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>1</u> TOWNSHIP <u>20S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3575' GL, 3585' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull rods, pump & tbg., spot perf. acid fr. 3453' to 3643' & perf. 5-1/2" csg. opposite G/SA zone selectively fr. 3453' to 3643' w/2 SPF. Set pkr. at 3500' & acidize perfs. fr. 3563' to 3643' w/2000 gal. 20% NE FE HCl acid using ball sealers & swab test. Set bridge plug at 3540', pkr. at 3350' & acidize perfs. fr. 3453' to 3491' w/1500 gal. 20% NE FE HCl acid using ball sealers. Swab test. Recover bridge plug, re-run tbg., pump & rods and resume prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E.B. Fisher TITLE Supy. Adm. Ser. DATE 7-12-83

ORIGINAL SIGNED BY JERRY SEXTON
 APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE JUL 14 1983

CONDITIONS OF APPROVAL, IF ANY: