

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06365
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Northeast Drinkard Unit
8. Well No.	318
9. Pool name or Wildcat	North Eunice Blinbry-Tubb-Drinkard
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3478' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> INJECTOR <input type="checkbox"/>	
2. Name of Operator Shell Western E&P, Inc.	
3. Address of Operator P.O. Box 576, Houston, TX 77001 Attn: S.A. Galik - 5239 WCK	
4. Well Location Unit Letter R : 1650 Feet From The South Line and 1980 Feet From The East Line Section 2 Township 21S Range 37E NMPM Lea County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Deepen and Convert to Injector ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/12 To 10/25/95

POOH w/Prod Eqmt. TAG fill @ 5894'. DO to 5915'. Circ hole clean. Start drilling new hole. Mill to 5932'. RIH w/bit and TAG @ 5932'. Drill to 5937. POOH w/tbg and tools. RIH w/mill and tag @ 5937'. Mill to 5941'. Circ hole clean. RIH w/bit and drill to 5986'. RIH w/PKR and set @ 5740'. AT w/6000 gal 20% HCL w/rock salt. Rel PKR. RIH w/Guiberson Uni VI PKR and set @ 5711'. Tst csg @ 500 PSI (Chart attached). NU wellhead. CTI
Return well to Injection.

NMOCD Administrative Order No. WFX-674

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley A. Galik TITLE Mgr. Reg. & Permitting DATE 1/26/96
TYPE OR PRINT NAME For: G. S. Nady TELEPHONE NO. 713/544-4219

(This space for State Use)

APPROVED BY JERRY SEXTON
SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 6 1996
CONDITIONS OF APPROVAL, IF ANY:

