

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFINISH OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Form or Lease Name E. L. Steeler WN
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico	9. Well No. 1 4
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 23S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Langlie Mattix 7R
15. Elevation (Show whether DF, RT, GR, etc.) 3324.4' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

TD 3594', PBD 3585'. Presently completed in perfs 3541-82'. This well is presently shut in because it was uneconomical to produce. Propose to add perfs, same zone, and treat in the following manner:


1. Rig up, kill well & install BOP.
2. Make trip w/bit & scraper.
3. RIH w/treating pkr & set @ 3500'.
4. Acidize perfs 3541-3582' w/2000 gals 50/50 15% HCL/xylene. SI overnight, swab back load & test
5. POH w/pkr.
6. Run GR Corr log, perforate Langlie Mattix 3462-3517' w/8 holes.
7. RIH w/RBP & trtg pkr on 2-7/8" tbg, set RBP @ 3530'. Spot acid across perfs, set pkr @ 3300' & acidize perfs 3462-3517' w/1000 gals 15% HCL-LSTNE acid using 12 - 7/8" RCN ball sealers.
8. Release pkr & lower to 3520', reset @ 3300'.
9. Frac perfs 3462-3517' w/10,000 gals slick 9# brine cont'g 20,000# 20/40 sd. Swab back until sand influx stops. Retrieve BP.
10. RIH w/completion assy & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Dist. Drlg. Supv. DATE 7/26/76

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:



ATLANTIC RICHFIELD COMPANY
Blow Out Preventer Program

Lease Name E. L. Steeler WN

Well No. 4

Location 660' FSL & 660' FWL
Sec 19-23S-37E, Lea County

BOP to be tested before installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.